WARRANTY INFORMATION BULLETIN

WIB 2015-04 5/05/2015

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

RCTI for SRS Harness Adjustment

This bulletin is to advise Dealers of a RCTI invoice which was raised by MMAL in the last week of April 2015.

This invoice is for Dealers who were entitled to an additional payment due to the time increase for Triton Dual Cab SRS harness replacements which could not be back dated in SAP claims. MMAL will follow up with a detailed report that shows the warranty claim number and the amount per claim. This will be sent to the Service Manager email address as recorded in SAP.

More detailed information will be provided at the Service Manager meetings being held during the month of May 2015.

Ian Matthews
Warranty Manager
National Service

To contact Warranty Payments Administration:
Warranty Telephone: 1300130099 option 2
option 4

e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au

Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039