WARRANTY INFORMATION BULLETIN

WIB 2016-03 9/03/2016

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

Pajero Sport Labour Operation Codes

MMAL Warranty Admin wish to advise that effective from 17th February 2016, the QE Pajero Sport labour operation times are now loaded in to the warranty system.

The Pajero Sport model is not available in the current version of the Operation Code Manual but dealers can still search for labour operation codes using either NS-NW Pajero or PB Challenger model to obtain the codes. When the claim is simulated the applicable labour operation time will be populated in the claim.

If there is no labour operation code available because the part being replaced is unique to Pajero Sport, please contact MMAL Warranty Admin who can advise what labour operation code to use.

Ian Matthews
Warranty Manager
National Service

To contact Warranty Payments Administration:
Warranty Telephone: 1300130099 option 2 option 4
e-mail: warrantyadmin@mmal.com.au mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042 PO Box 8 Melrose Park SA 5039