MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2016-05 26/04/2016

This Bulletin forms part of the Warranty Procedure Manual.

ATT: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

Claiming for Engine Overheat Post Campaign

NOTE: This WIB should be read in association with **GL-16-016.**

Claims for vehicles previously serviced under Campaign 020116 that subsequently fail with any of the following causes:

- *Engine overheat has occurred due to excessive loss of coolant that is caused by repetitive coolant evaporation.*
- *Localised coolant evaporation has occurred after high load driving such as towing heavy loads.*
- *The sealing condition is not adequate at the upper surface of cylinder block (due to the surface roughness) engine coolant blow-by has occurred promoting overheating.*

must be claimed as a Warranty Claim type ZC01 or Parts Claim type ZC06.


The claim must contain reference numbers of any SCA, TSR and or DQR that has been submitted in support of the claim. In addition, the claim number for the previous campaign claim must also be listed. These reference numbers are to be listed in the Notes section of the claim.

It will also be necessary to submit a SCA Request. The SCA will be used in all cases (i.e. in and out of warranty), DO NOT submit a Goodwill Request.

To identify that this SCA is in support of a claim for a condition previously identified as a Campaign, please select Claim Type 'Campaign', under the SCA request section ‘General Repair Data’. In the Notes section of SCA, under ‘Reason for SCA’ add "Post 020116 Service Campaign engine overheat.

Please see image on the next page for an example of selecting claim type “Campaign”.

To contact Warranty Payments Administration:
Warranty Telephone: 1300130099 option 2 option 4
e-mail: warrantyadmin@mmal.com.au mmal_warranty_admin@mmal.com.au
Address: 1284 South Road Clovelly Park SA 5042 PO Box 8 Melrose Park SA 5039



Ian Matthews
Warranty Manager
National Service

To contact Warranty Payments Administration:
Telephone Warranty Hot Line: 1300130099 option 2 option 4

E-mail: mmal_warranty_admin@mmal.com.au

Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039