MITSUBISHI MOTORS

WARRANTY INFORMATION BULLETIN

WIB 2016-09 21/09/2016

This Bulletin forms part of the Warranty Procedure Manual.


ATT: SERVICE MANAGERS/WARRANTY ADMINISTRATORS

Operation Code Manual R2.9

MMAL are pleased to advise that the latest release of the Operation Code Manual (OCM R2.9) is now available via the SAP Portal.

How to access the manual

The manual can be accessed directly from a link under "Detailed Navigation" as shown in the screenshot below.



NOTE: Your screen may look slightly different from the one displayed depending on access.

Changes in OCM R2.9

1. New Models added:
    a. Pajero Sport QE
2. Various data changes
3. Revision number brought into line with MMC manual

Ian Matthews
Warranty Manager
National Service

To contact Warranty Payments Administration:

Warranty Telephone: 1300130099 option 2
option 4

e-mail: warrantyadmin@mmal.com.au
mmal_warranty_admin@mmal.com.au

Address: 1284 South Road Clovelly Park SA 5042
PO Box 8 Melrose Park SA 5039