MITSUBISHI MOTORS
Drive your Ambition

MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395

Head Office
1 Tonsley Boulevard, Tonsley, SA, 5042
PO Box 8, Melrose Park, SA, 5039
Ph: +61 1300 13 12 11

WIB-2020-01

25th September 2020

Attention: Service Managers, Service & Warranty Personnel

Subject: Warranty Administration Communication

Dear Ladies and Gentlemen,

This bulletin covers Communication between MMAL Warranty Admin and Dealers.

For some time, MMAL Warranty Admin have not communicated directly to Dealers regarding warranty process and procedure related issues. Going forward, Warranty Admin will reintroduce Warranty Information Bulletins, commonly referred to as a WIB, to communicate relevant information to Dealer Warranty and Service staff.

WIB's use the naming convention: WIB-20xx-yy where the x is the year and the y is the number of the bulletin in that year with the subject clearly identified at the top of the WIB.

When a WIB is issued, an email will be sent to the email groups Dealer Service Manager, Dealer Service and Dealer Warranty and the bulletin will be attached to the email.
A copy of the bulletin will also be available on the Mitsubishi Portal for future reference.

Warranty Bulletins (shown below) are located on the portal on the Service Home Page. This page is accessed via the path: My Work > Service.



To make sure Dealers receive all relevant communications Dealers must ensure all employee email addresses are correct and maintained in the applicable email group. Groups should be regularly reviewed and any incorrect or redundant email addresses removed. Please check with the Dealer Portal Administrator within your Dealership.

MITSUBISHI MOTORS
Drive your Ambition

MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395

Head Office
1 Tonsley Boulevard, Tonsley, SA, 5042
PO Box 8, Melrose Park, SA, 5039
Ph: +61 1300 13 12 11

All correspondence from Dealers to Warranty Admin is via email. The Warranty Admin email address is: warrantyadmin@mmal.com.au

The "Subject" field of the email must contain your Dealer code, SAP Claim Number and a brief description of the issue. The "Body" of the email should contain a brief and concise description of the assistance required. Please ensure any relevant documents are attached.
Refer to a previous warranty bulletin WIB-2014-04 which provides more detail.



Fiona Lamond
Warranty Administration Manager