MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395

Head Office
1 Sir Richard Williams Ave,
Adelaide Airport, SA 5950
PO Box 249, Export Park, SA 5950
Ph: +61 1300 13 12 11

WIB-2022-01

4th February 2022

Attention: Service Managers, Service & Warranty Personnel


Subject: Warranty Portal Changes

Dear Ladies and Gentlemen,

Recent changes to the warranty portal have resulted in the following changes to the claim submission process.

1. Copying Authority to Claim

The Repair date and Mileage fields are now cleared as part of the copy process. Please **UPDATE both fields** with the **details relevant to when the repair was actually undertaken BEFORE** selecting **Submit**.
The Repair date cannot be updated by the Dealer after claim submission is attempted even if a VSR error is present.



2. Claim Type Menu – changed selections

The following "Claim Types" are no longer available in the drop down selection

- Service Claim Authority

MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395

Head Office
1 Sir Richard Williams Ave,
Adelaide Airport, SA 5950
PO Box 249, Export Park, SA 5950
Ph: +61 1300 13 12 11


- Goodwill Authority
- TSR - Technical Support Request

a. Service Claim Authority and Goodwill Authority

An "Authorisation required" check box has been introduced as shown below.

Select the "Claim Type" appropriate to the final claim, e.g. after authorisation the claim submitted will be a Warranty claim, then check the "Authorisation Required" box and continue as normal to create an authorisation.

The authorisation type created will be determined by the system and is based on the information entered about the repair i.e. VIN, repair date/mileage and position code.




b. Technical Support Requests

Please refer to Dealer communication -
"**MMAL - 22005 Introduction to the Technical Enquiry Support Solution**" issued 19/01/2022 for full details.
There is also a "Training Materials" tile on the warranty portal entry screen which contains all the relevant documents and a process video.

a. In brief, an enquiry of the TESS system should be undertaken BEFORE proceeding to create a TSR. If there is no Published TSR information that can assist with a concern, a TSR may be created by clicking the **"Issue not resolved (Create TSR)"** button in the bottom right of the Technical Enquiry Support System window shown below.

MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395

Head Office
1 Sir Richard Williams Ave,
Adelaide Airport, SA 5950
PO Box 249, Export Park, SA 5950
Ph: +61 1300 13 12 11



Yours sincerely,

Fiona Lamond
Warranty Administration Manager