MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395

Head Office
1 Sir Richard Williams Ave,
Adelaide Airport, SA 5950
PO Box 249, Export Park, SA 5950
Ph: +61 1300 13 12 11

WIB-2022-03

7th September 2022

Attention: Service Managers, Service & Warranty Personnel

Subject: Reminder - Triton Mi-Display Launch

Dear Ladies and Gentlemen,

MMAL Warranty Administration wish to remind all Dealers of Bulletin MMAL-21260 which relates to MY22 MR Triton Mi-Display unit.
The bulletin and all other communication applicable is available on the MMAL Dealer Portal Service Homepage.

Service staff may also benefit from familiarising themselves with Bulletin MMAL-22134 and Bulletin MMAL-22135 on the Parts Homepage.

It is important that the correct process for Mi-Display unit repair is followed.

Failure to adhere to the bulletin requirements may result in a claim not being paid or the payment reversed if the repair is later identified e.g. as a result of audit, as not complying with MMAL requirements.

Please ensure all Service staff within your Dealership have read ALL the communications that are relevant to their role and are familiar with the processes.

.

Yours sincerely,



Fiona Lamond
Warranty Administration Manager