MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395

Head Office
1 Sir Richard Williams Ave,
Adelaide Airport, SA 5950
PO Box 249, Export Park, SA 5950
Ph: +61 1300 13 12 11

WIB-2022-04

7th September 2022

Attention: Service Managers, Service & Warranty Personnel

Subject: Exchange audio unit claims

Dear Ladies and Gentlemen,

MMAL Warranty Administration wish to remind Dealers that when an audio unit is fitted to a vehicle under an exchange program, a warranty claim must be submitted at the time of repair.

Exchange units issued by the vendor will be cross-referenced against warranty claims submitted.
Failure to submit claims in line with warranty submission guidelines may result in Dealers being billed for audio unit repairs, if proof of repair is not provided.

Kenwood and Mitsubishi Electric exchange request forms must be completed **IN FULL** – including the audio unit serial number (unless otherwise arranged with MMAL).
Exchange units will not be issued until a correctly completed form is received.
Incorrect or incomplete forms will delay shipping of the exchange unit.

For any other units, please refer to the respective bulletins for ordering instructions.

When raising a warranty claim for an exchange audio unit, use the cause part number **XAUDIO**.
If the unit was removed to obtain the serial number, refer to Warranty Bulletin WIB-2008-19 for claim instructions. Do not tick the Repaired box.

Yours sincerely,



Fiona Lamond
Warranty Administration Manager