MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395

Head Office
1 Sir Richard Williams Ave,
Adelaide Airport, SA 5950
PO Box 249, Export Park, SA 5950
Ph: +61 1300 13 12 11

WIB-2023-02

10th March 2023

Attention: Service Managers, Service & Warranty Personnel
Subject: Changes to Dealer Portal Claim Field Captures

Dear Valued Business Partners,

MMAL Warranty Administration advise that effective from Monday 13th March, additional data entry fields will be available during claim creation.

On the initial **Claim Creation** screen, the following new fields are displayed:

- **Failure Date**
- **DTC Reported**

Under the **Text Icon** on the Claim Detail screen, "Claim Remarks" is replaced by separate entry fields for the Concern, Cause & Correction ("CCC") information. "CCC" entries are required in the following fields:

- **Customer Concern**
- **Cause of Failure**
- **Correction/Repair Details**

Dealers are required to provide Concern, Cause & Correction detail to support each claim.

Before submission, please check that all claim information provided is accurate and complete. This ensures the efficient processing of claims for both the Dealer and MMAL.

Thank you for your support

Yours sincerely,



Fiona Lamond
Warranty Administration Manager

Please note:
1: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer internal use only. It must not be provided or supplied to third parties.
2: This WIB forms part of the Warranty Procedure Manual
Copyright © Mitsubishi Motors Australia Limited

MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395


Head Office
1 Sir Richard Williams Ave,
Adelaide Airport, SA 5950
PO Box 249, Export Park, SA 5950
Ph: +61 1300 13 12 11

Claim Creation screen

Failure Date

The date the Customer Concern was first reported to the dealer.
Failure Date may be prior to (e.g. reported on a previous Repair Order) or the same as the actual Repair Date.


This field is mandatory.



DTC Reported

Where a DTC has been registered that is relevant to the repair, enter the first five (5) characters of the displayed DTC in the field(s) provided, e.g. P06B0-11 is entered as P06B0.
Where multiple DTC are displayed, up to five (5) individual codes can be entered.
If no DTC entry is applicable, the fields can be left blank.

Note: Express van DTC do not fit this format and must be entered in the "Cause of Failure" tab.




Note: currently the dealer cannot edit these fields once the claim is created. To alter or add codes email warrantyadmin@mmal.com.au

Please note:
1: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer internal use only. It must not be provided or supplied to third parties.
2: This WIB forms part of the Warranty Procedure Manual
Copyright © Mitsubishi Motors Australia Limited


MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395

Head Office
1 Sir Richard Williams Ave,
Adelaide Airport, SA 5950
PO Box 249, Export Park, SA 5950
Ph: +61 1300 13 12 11

Entered DTC values will display under the "Extensions" icon as shown below:



Where multiple DTC are recorded



Claim Detail screen / Text Icon


Dealers are required to provide information regarding the Concern, Cause & Correction under the listed headings.
Please provide accurate, brief and concise information that describes the reported concern, technicians' diagnosis, and the rectification work undertaken.

Please note:
1: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer internal use only. It must not be provided or supplied to third parties.
2: This WIB forms part of the Warranty Procedure Manual
Copyright © Mitsubishi Motors Australia Limited


MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395

Head Office
1 Sir Richard Williams Ave,
Adelaide Airport, SA 5950
PO Box 249, Export Park, SA 5950
Ph: +61 1300 13 12 11

Customer Concern - Ensure the Customer Concern is recorded accurately, including a description of the symptoms and circumstances, in a clear and concise manner.



Cause of Failure – Record the Technicians' diagnosis of the cause of the customer concern.




Please note:
1: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer internal use only. It must not be provided or supplied to third parties.
2: This WIB forms part of the Warranty Procedure Manual
Copyright © Mitsubishi Motors Australia Limited

MITSUBISHI MOTORS AUSTRALIA LIMITED
ABN 53 007 870 395

Head Office
1 Sir Richard Williams Ave,
Adelaide Airport, SA 5950
PO Box 249, Export Park, SA 5950
Ph: +61 1300 13 12 11

Correction/Repair Details – Record the details relating to the method of the repair/correction that was undertaken.



Accurate recording of DTC and CCC details is required to assist MMAL during claim review and adjudication and provide additional insight to, and support for problem identification and resolution.

Please note:
1: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer internal use only. It must not be provided or supplied to third parties.
2: This WIB forms part of the Warranty Procedure Manual
Copyright © Mitsubishi Motors Australia Limited