**YR54/022** **Issue Date: 13/09/2002**

**Buzzing Noise Though Speakers (Clarion CD-Tuner)**

A buzzing noise may be heard with headlights and instrument lights dimmed in both CD and FM-AM tuner modes, particularly with volume level set low.

**Production Fix:**
Two earth braids were fitted between the audio PCB and chassis From serial no c0013329 with progressive introduction during September 2002

**Field Fix:**
During the warranty period request an exchange audio unit.

Note: All Units Supplied From Clarion From August 2002 Have Been Updated to include this “fix”.

Ref:TC54-2002

**Please note:** The information contained in this section is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.

MITSUBISHI MOTORS
MITSUBISHI *Spirited Cars for Spirited People*