# HOTLINE FIX

| | | |
|---|---|---|
| **Group: 11 – Engine** | **Original Date: 17th January 2017** | **No. ZJ11-001** |
| **Model: ZJ Outlander** | **Subject: Flat spot on acceleration** | |
| **Revised on** ..... (date)<br>**Revised on** ..... (date)<br>**Revised on** ..... (date) | Michael Miller<br>Manager,<br>Field Service. |  |
| **MMAL Ref** TSL1501013 | **Document consists of 2 pages.** | |

1. S**ubject**: Flat spot on acceleration.

2. **Applicable Vehicle:**

| MY | Model | Engine | Transmission |
|---|---|---|---|
| 13 | ZJ OUTLANDER | 4N41 | W6AJA |

3. **Possible Cause:** The amount of fuel that was injected under acceleration was reduced to minimise transmission shift-shock and reduce the amount of smoke emitted from the exhaust tail pipe. This resulted in a flat spot when accelerating from stand-still and/or low speed acceleration.

4. **Improvement:** Engine ECU software update will change the fuel injection control and improve acceleration.

5. **Field Fix/Action:** Install the new Engine ECU software using CD-ROM number **CD3A15011**, on a customer complaint basis.

6. **Parts Information:**

| MY | Data No. | ECU P/N | Software P/N | |
|---|---|---|---|---|
| | | | New | Current |
| 13 | 1862C055 | 1860B815 | 1860B815-05 | 1860B815-04 |

***Disclaimer:*** *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.

**Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff**

**Copyright © Mitsubishi Motors Australia Limited**
**Please note:** The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.

(6) **Warranty Information:** Standard terms and conditions apply

| Hotline fix ZJ11-001 | Flat spot on acceleration | | |
|---|---|---|---|
| Claim header tab | Claim Type | ZC01 | |
| Items tab | Item 1 | Item Type | Misc Parts |
| | | Part No | Reflash |
| | | Dealer Quantity | 1 |
| | | Claimed Amount | $0.00 |
| | | Part Causing Damage | ☑ |
| | | Position Code | 138501 |
| | | Diagnosis Code | 49 |
| | | Complaint | 04 |
| | Item 2 | Item Type | Labour Value |
| | | Labour Operation | 138501 13 |
| | | Dealer Quantity | 1 |