



GOOD SHOWROOM · AFTERSALES MODULE

Warranty Evidence Capture

Technician-Guided Capture App + Warranty Clerk / Manager Review Portal

Workshop-first, multi-brand workflow for capturing complete warranty evidence at source, enforcing OEM rules before submission and delivering a correctly named, audit-ready case pack to warranty staff.

Document type	Functional & technical scope · implementation-ready
Prepared for	Booran Motor Group · Aftersales / Warranty operations
Prepared by	OmniSuiteAI Pty Ltd
Date	3 September 2026
Version	1.0 · Internal draft for review
Related source	BYD-WB-2602-02 Attachment A · Photo & Video Checklist
Related platform	Good Showroom · Voice to Tech (previously deployed)
Classification	INTERNAL USE ONLY

INTERNAL USE ONLY — Proprietary product, workflow, security and implementation scope. Distribution is restricted to authorised OmniSuiteAI and Booran Motor Group stakeholders.

SCOPE FOCUS Guided technician capture · Mandatory evidence gates · Voice to Tech notes · Multi-brand rule packs · Clerk review and OEM-ready exports

1. Purpose

This scope defines a workshop-first Warranty Evidence Capture system for Booran Motor Group. Technicians log a warranty ticket on a mobile-first app that walks them, step by step, through every required piece of evidence for that brand and fault type. The app will not let a case leave the workshop incomplete. Once captured, the case file is pushed to a review portal used by warranty clerks, service managers and service advisors.

The attached BYD checklist is the first brand pack. The same process applies across Booran brands (BYD, Hyundai, Kia, MG, Chery, Mitsubishi, Nissan, Isuzu UTE, Škoda, Suzuki, Ford, Toyota, GMSV and others). Brand-specific photo, video and diagnostic rules are configured once and then enforced at the point of capture.

SCOPE NOTE

Why this exists

OEM warranty teams return or delay claims that are missing VIN, odometer, fault location, part serials, diagnostics or correctly named attachments. That cost sits with the dealer: extra technician time, clerk chase-up, and delayed reimbursement. This module moves compliance to the workshop floor so the case file that reaches the clerk is already submission-ready.



2. Objectives and success criteria

2.1 Objectives

- Eliminate incomplete warranty evidence packs before they reach the clerk.
- Cut technician cognitive load: one guided path, one case, no separate checklist to remember.
- Capture vehicle identity in seconds (VIN, odometer, front-of-vehicle, dealer/RO) regardless of brand.
- Reuse Voice to Tech so notes are dictated on the workshop floor, not typed later.
- Give clerks, managers and advisors a single case file (photos, video, notes, diagnostics, naming already applied) that can be marked Submitted or Flagged.
- Support every Booran brand from one app, with OEM rules that can be updated without a rebuild.

2.2 Success criteria (acceptance)

- A technician can open a new warranty ticket, identify the vehicle, and complete a standard Tier 1 pack without leaving the app.
- The app blocks Next / Submit on any mandatory item that is missing, unreadable, or of the wrong media type.
- Every attachment is auto-named to the OEM convention before it leaves the device (e.g. [DealerRONumber]FrontOfCar.jpg).
- Voice notes transcribe into the case using the existing Voice to Tech pipeline and remain editable.
- Clerks can open a completed case, review every artefact against the checklist, mark Submitted or Flag for more evidence, and download a submission pack.
- BYD Attachment A rules are live as Brand Pack v1. A second brand pack can be added by configuration, not code.

3. Users and access

Role	Primary surface	What they do
Technician	Mobile / tablet PWA (workshop)	Start ticket, identify vehicle, follow guided evidence steps, dictate notes, submit complete case.
Warranty clerk	Web portal (desktop)	Queue of new cases, review pack, mark Submitted, flag gaps, download named pack for OEM / DMS.
Service advisor	Web portal	See case status against an RO, add customer-facing context, chase flagged items with the tech.
Service / aftersales manager	Web portal	Site and group dashboards, exception queue, incomplete / aged cases, training gaps by technician.
Group admin	Web portal (admin)	Users, sites, brands, checklist packs, naming templates, retention settings.

Access is site-aware. A technician at Cranbourne BYD sees Cranbourne as the default dealer. A group clerk can filter across sites. Authentication uses Booran accounts (SSO if available; otherwise secure email/password + MFA for portal roles).

4. Solution overview

Two surfaces, one case file.

A. Technician Capture App (workshop)

- Mobile-first Progressive Web App, phone and tablet, installable to home screen. No app-store dependency for v1.
- Designed for one-handed use in a workshop: large tap targets, camera-first steps, voice notes, offline draft.
- Guided wizard driven by the active Brand Pack + fault type. Progress bar and remaining mandatory items always visible.
- Cannot mark a case Complete until every mandatory artefact for that path is present and passes basic quality checks.



B. Warranty Review Portal

- Desktop-first web portal for clerks, advisors and managers.
- Case inbox, case file viewer (gallery + video + notes + diagnostics), status actions, flags with reason codes, downloadable submission pack.
- Read-only audit trail: who captured what, when, on which device, and every status change.

C. Shared case engine

- One Warranty Case object per RO / concern (or per claim line if the brand requires it).
- Brand Pack rules evaluate live as the technician works. Changing fault type mid-job recalculates Tier 2 requirements.
- Media stored against the case with the OEM file name applied at capture time, not at download time.

5. Technician app — guided workflow

The app is a linear, gated wizard. Optional steps appear only when the Brand Pack says they apply. The technician can jump back to a completed step to recapture, but cannot skip forward past a hard gate.

5.1 Step 0 — Start a warranty ticket

- New case from home screen (primary action) or resume a draft.
- Select site / dealer (defaults to the technician's home site; override if working across rooftops).
- Select brand from the sites authorised brands. This loads the Brand Pack (BYD Attachment A for BYD; equivalent pack for other OEMs).
- Enter or scan Repair Order number. RO is the master key for attachment naming and clerk matching. Format validated per site convention.
- Optional Claim Number if already issued by the OEM / DMS; otherwise left blank for the clerk.
- Technician identity is taken from the signed-in user. Date/time is stamped automatically.

5.2 Step 1 — Vehicle identification (fast path)

This step is brand-agnostic and must be completable in well under a minute on a typical job. It satisfies the identity block on every OEM checklist (VIN, odometer, front-of-vehicle, dealer).

Capture	How the technician does it
VIN	Camera scan of VIN plate or windscreen label with on-device OCR. Fallback: scan a VDS / diagnostic printout. Final fallback: manual entry with check-digit validation where the brand supports it. Live preview must show the VIN clearly before Accept.
Odometer	Photo of the cluster. Prompt changes by powertrain: EV mileage; EV + HV for hybrid / PHEV. Technician confirms the reading; digits are OCR'd into the case field and remain editable.
Front of vehicle	Guided camera overlay (vehicle fills frame, number plate readable where present). Used as the identification reference shot.
Make / model / year	Decoded from VIN where a decoder is available; otherwise short pick-lists scoped to the selected brand. Technician confirms, does not retype.
Powertrain flag	EV / Hybrid / ICE — drives odometer prompt and later Tier 2 packs (HV battery, charging).

Gate: VIN photo accepted, VIN string populated, odometer photo accepted, odometer reading populated, front-of-vehicle photo accepted. No onward progress without all four.



5.3 Step 2 — Concern and fault type

- Short concern title (typed or dictated).
- Fault category selected from the Brand Pack list. For BYD seed pack:
 - Oil leaks or seepage
 - ECU or sensor internal faults
 - Software updates or program refreshes
 - Battery and high-voltage (HV) components
 - Charging system faults
 - Powertrain, chassis or body component faults
 - General / other (Tier 1 only)
- Part being replaced? Yes / No. If Yes, Old and New serial steps become mandatory.
- Repair stage: Pre-repair only / During repair / Repair complete. Controls whether before/after photos are required now or later.
- Noise or operational fault not easily shown in stills? Yes / No. If Yes, video step becomes mandatory.
- Diagnostics available? Yes / No. If Yes, VDS / DTC / calibration / software evidence becomes mandatory.

Selecting a Tier 2 category immediately appends that category's extra steps to the wizard. The remaining-items counter updates in place. Annex 2-style component rules (when supplied per brand) attach at this point as additional required shots, not as a separate document the technician has to read.

5.4 Step 3 — Guided evidence capture (Tier 1 always)

Each evidence item is its own screen with: instruction, example thumbnail (from the Brand Pack), capture button, retake, and Accept. The technician never sees a wall of checkboxes.

Evidence item	Required when	In-app guidance
VIN photo	Always	Plate or VDS printout. VIN characters must be readable. OCR confirms match to Step 1 VIN.
Odometer photo	Always	Cluster in frame. EV + HV callout on hybrid. Reading confirmed.
Front of vehicle	Always	Identification reference. Overlay guides framing.
Fault — close-up	Always	Defect fills the frame. Flash / torch toggle. Blur warning if unusable.
Fault — location	Always	Wider shot showing where the defect sits on the vehicle / system.
Old part serial / barcode	Part replaced	Barcode / QR scan first; photo of the marking as proof. Serial written into the case.
New part serial / barcode	Part replaced	Same as old part. Warns if new serial equals old serial.
Before repair photo(s)	Where applicable	Triggered by repair stage and fault type. Count comes from Brand Pack.
After repair photo(s)	Repair complete	Same framing as before, so clerks can compare.
Diagnostic evidence	Where applicable	Photo of VDS / DTC screen, calibration result or software version. Multiple shots allowed. Optional PDF upload from workshop PC later via portal.
Video (.mp4)	Noise / operational	In-app recorder, suggested max duration (e.g. 30–60s), before and after clips if the Brand Pack asks for both.

5.5 Step 4 — Tier 2 extra evidence

Rendered only when the selected fault type requires it. Each Brand Pack defines the extra shots, videos or documents. For the BYD seed pack the categories in Attachment A are the gates; the detailed shot list is sourced from Annex 2 when Booran supplies it (or from an OmniSuiteAI transcription of Annex 2 if provided). Until Annex 2 is loaded, each Tier 2 category still requires at least one additional close-up and one contextual shot beyond Tier 1, plus a dictated note describing what the extra evidence shows.

Examples of how this is intended to work once Annex 2 (or the equivalent OEM chapter) is configured:



- Oil leak / seepage — dry-area reference, leak origin, extent after a defined wait, fluid colour, surrounding components.
- ECU / sensor internal — connector condition, pin face, mounting, related harness, DTC screenshot.
- Software update / refresh — before version, after version, VDS confirmation screen.
- Battery / HV — isolator state, warning labels, module / pack identifier, insulation / torque evidence as specified, HV-safe work confirmation.
- Charging system — inlet / gun, portable charger or AC/DC equipment ID, charge-session screenshot where available.
- Powertrain / chassis / body — specified angles, part identifiers, adjacent damage to rule out impact.

5.6 Step 5 — Notes via Voice to Tech

Notes are available on every step and as a dedicated wrap-up screen. Capture uses the previously deployed Voice to Tech capability rather than a new dictation stack.

- Hold-to-talk control on every evidence screen and a full Notes step at the end.
- Workshop-noise handling consistent with the existing Voice to Tech deployment (same engine, same endpoint, same Australian-English model).
- Transcript appears immediately, editable by tap. Original audio is retained on the case for clerk playback if the transcript is disputed.
- Suggested note prompts change by step, e.g. “Describe the customer concern”, “What did you see on the leak?”, “What DTC and freeze-frame did VDS show?”.
- Technician can pin a note to a specific photo or video so the clerk reads context next to the artefact.
- No requirement to type on a greasy screen. Keyboard remains available as fallback.

5.7 Step 6 — Review and submit from the workshop

- Single review screen: identity block, checklist with green ticks / red gaps, thumbnail strip, notes, video count.
- Submit to Portal is disabled until every mandatory item is green.
- On submit: media is uploaded (or queued if offline), OEM file names are frozen, case status becomes Awaiting Review, technician receives a confirmation with RO and case ID.
- Technician can still add after-repair photos later by reopening the same RO case (status returns to Awaiting Review if the clerk has not yet marked Submitted).

6. Quality gates (so clerks are not used as a safety net)

The product promise is that Flag for incomplete evidence should be rare. Gates are enforced on device, not only in the portal.

- Mandatory vs optional is driven by Brand Pack + answers in Step 2. Optional items never block submit.
- Photo quality: minimum resolution, reject near-black / near-white frames, warn on heavy blur, warn if VIN OCR does not match the typed/scanned VIN.
- Video: container must be mp4; duration within Brand Pack limits; audio present when the fault is noise-related.
- Serials: barcode decode preferred; photo still required as proof.
- Naming: applied automatically. Technician never types a file name.
- Duplicate-case warning if an open case already exists for the same RO + brand.

If a clerk still flags a case, the technician sees a precise list of missing items (not a generic “incomplete”) and is dropped back onto those steps only.



7. Attachment naming and pack structure

Matches the BYD attachment standard and is templated per brand so other OEMs can differ without code changes.

BYD seed templates (applied automatically)

Type	Pattern
Photos (.jpg)	[DealerRONumber]FrontOfCar.jpg [DealerRONumber]NewPartSerial.jpg [DealerRONumber]OldPartSerial.jpg plus generated names for VIN, Odo, FaultClose, FaultLocation, Before, After, DTC, etc.
Documents (.pdf)	[DealerRONumber].pdf [DealerRONumber]SubletInvoice.pdf [DealerRONumber]TechClockings.pdf
Videos (.mp4)	[DealerRONumber]KnockingNoise(Before).mp4 [DealerRONumber]KnockingNoise(After).mp4 (descriptor taken from fault type / technician label)

DealerRONumber is the site RO as entered in Step 0. Additional descriptors are taken from the evidence item key, not free-typed by the technician. The download pack in the portal uses these names on disk so the file the clerk attaches to the OEM DMS is already compliant.

8. Warranty Review Portal

8.1 Inbox and filters

- Default view: Awaiting Review for the user's site(s), newest first.
- Filters: site, brand, technician, status, date, RO, VIN, flagged only, aged beyond X hours.
- Status values: Draft (on device) · Uploading · Awaiting Review · Flagged · Submitted · Closed / Withdrawn.

8.2 Case file viewer

- Header: brand, site, RO, VIN, odometer, technician, timestamps, claim number.
- Checklist panel mapped to the Brand Pack, each item linked to its artefact.
- Gallery with full-size preview, pinch/zoom, before/after compare slider where both exist.
- Inline video player.
- Notes thread with Voice to Tech transcript + audio playback + pin-to-artefact links.
- Diagnostic images / PDFs.
- Activity log.

8.3 Actions

- Mark Submitted — case is locked for technician edits (manager can unlock). Clerk records OEM claim number if not already present.
- Flag for additional / incomplete evidence — reason codes (missing shot, unreadable VIN, wrong angle, no serial, no DTC, video too short, other) plus a free-text instruction. Technician is notified in-app and by email/SMS if configured.
- Download submission pack — zip of correctly named files plus a one-page case summary PDF (identity, concern, checklist, note extract).
- Add clerk note — internal, not shown as technician workshop notes.
- Attach extra document — sublet invoice, tech clockings, OEM authorisation. Named per template.

Flag exists because the real world is messy (customer left, part on backorder, lighting). It is not the primary control. The primary control is the gated technician app.



8.4 Manager view

- Counts: cases opened, submitted same day, flagged, resubmitted, average time workshop-to-submitted.
- Flag reasons ranked — used as a training feed for technicians who repeatedly miss the same shot.
- Per-site and per-brand breakdown across the group.

9. Brand Pack engine (multi-brand by design)

Booran is not a single-franchise group. The app must not be a BYD tool with other brands bolted on. BYD Attachment A is Brand Pack #1, not the product.

What a Brand Pack contains

- Brand identity and applicable Booran sites.
- Vehicle ID rules (odometer flavour, VIN sources).
- Tier 1 item list (usually common across brands).
- Fault-type tree and Tier 2 extras.
- Per-item instruction text, example image, min count, media type, max video length.
- File-name templates.
- Optional reference to a deeper annex (e.g. BYD Annex 2 – Details of Defect Photos Requirements) as structured extra shots per component.

v1 brand coverage

- BYD — full pack from Attachment A. Annex 2 loaded if/when the manual is provided.
- All other current Booran brands — Tier 1 common pack + a simple fault-type list + naming template, so every rooftop can use the app on day one.
- Further OEM annexes added as configuration work orders, not as new applications.

Group admin can clone a pack, edit item text, mark items mandatory/optional, and publish. Published packs version; in-flight cases keep the pack version they started on.

10. Voice to Tech — reuse, not rebuild

Voice to Tech is treated as an existing OmniSuiteAI capability already deployed for technician dictation. This module consumes it.

- Same speech-to-text pipeline and Australian workshop language model.
- Same authentication pattern so technicians do not hold a second voice credential.
- New work is the integration only: record control inside each evidence step, attach transcript + audio to the Warranty Case, pin notes to artefacts, surface playback in the portal.
- If Voice to Tech is unreachable, the app degrades to on-device keyboard and queues audio for later transcription — capture is never blocked by the voice service.

Assumption: OmniSuiteAI will confirm the existing Voice to Tech endpoint, auth method and any per-minute commercial terms before build. If the prior deployment needs a workshop-noise upgrade, that is a separate thin work order, not this scope.



11. Integrations

System	v1 posture	Intent
Voice to Tech	In scope	Dictation + transcript + audio attach.
Booran identity / SSO	Preferred	Portal and app login. Fallback: local accounts + MFA for clerks.
Dealer DMS / BYD DMS	Out of scope for v1 write-back	Case is complete before it hits the OEM DMS. Clerk downloads the pack and submits in the existing DMS. Read of RO header is a Phase 2 candidate if Booran nominates the DMS and grants access.
VIN decode	In scope (best-effort)	Populate make/model/year/powertrain. Manual confirm always available.
Good Showroom suite	Aligned	Same account model and visual language as other Booran Good Showroom modules where those exist, so technicians are not learning a third system.
Email / SMS notify	In scope (light)	Technician notified on Flag. Clerk notified on new Awaiting Review (digest or instant, configurable).

Explicit non-goal for v1: automatic claim creation inside any OEM warranty portal. This product produces a clean, named, complete case file. The clerk remains accountable for the commercial submission.

12. Non-functional requirements

12.1 Workshop reality

- Works on current iOS and Android phones/tablets used in Booran workshops; Chrome/Safari current two versions.
- Offline draft: identity, photos, video and audio are stored on device if workshop Wi-Fi drops. Upload resumes automatically. Submit is allowed only when all mandatory media has reached the server (or is queued with a clear “will submit when online” state that clerks can already see as Uploading).
- Camera and microphone permissions requested in context, not on first launch dump.
- Large controls, high contrast, readable in bright yard light and dim workshop light.

12.2 Media and retention

- Photos stored as JPEG; videos as MP4. Reasonable client-side compression so a full case uploads on typical site broadband without killing workshop Wi-Fi.
- Originals retained. Portal preview may use derivatives.
- Retention aligned to Booran / OEM warranty record-keeping (configurable; default 7 years).

12.3 Security and privacy

- Australian hosting. Data residency in Australia.
- TLS in transit, encryption at rest.
- Role-based access; site scoping; no technician can see another site’s cases unless granted.
- Customer personal information limited to what the RO already requires. No marketing use of case media.
- Privacy Act 1988 and APP-aligned handling. Media depicts vehicles and workshop activity, not customers’ faces by design; if a face is captured, clerks can request redaction (simple crop/blur tool in portal — Phase 2 if not in v1 core).
- Audit log retained for the same period as the case.

12.4 Performance

- Step transitions under one second on a mid-range workshop phone once assets are cached.
- Photo accept-to-thumbnail under two seconds.
- Portal case open (including first gallery) under three seconds on typical office broadband.



13. Out of scope (v1)

- Direct API write of the claim into BYD DMS or any other OEM warranty portal.
- Warranty adjudication, labour/parts costing, or claim-value calculation.
- Full Annex 2 component encyclopaedia until the source document is supplied.
- Customer-facing status tracking.
- Native App Store / Play Store binaries (PWA is the v1 delivery).
- Machine-vision pass/fail of defect type (possible later; not required to meet this checklist).
- Replacement of existing DMS time clocks, sublet or parts systems — the portal only attaches those PDFs if the clerk has them.
- Rebuild of Voice to Tech itself.

14. Assumptions and dependencies

- Booran nominates pilot site(s), pilot brand (recommended: BYD plus one ICE/hybrid brand), and a clerk champion.
- BYD Annex 2 is provided if Tier 2 is to be component-perfect rather than category-level in v1.
- Voice to Tech remains available to this module on the existing commercial footing.
- Technicians have a work phone or shared workshop tablet with camera and mic.
- RO numbers are unique per site and known to the technician at the point of capture.
- OmniSuiteAI is not the warranty decision-maker. The app collects evidence; OEM policy remains Annex / manual authority.
- Brand Pack content for non-BYD OEMs will be confirmed with each franchise aftersales lead; until then they run on the common Tier 1 pack.

15. Delivery phases

Phase	Focus	Exit
0 Discover	Confirm Voice to Tech hook-up, pilot rooftop(s), DMS download-only workflow, Annex 2 availability, user list.	Signed-off information architecture and Brand Pack v1 schema.
1 Capture app	Ticket start, vehicle ID fast path, Tier 1 wizard, Voice to Tech notes, offline draft, BYD pack live, common pack for other brands.	Pilot technicians complete real jobs without a paper checklist.
2 Portal	Inbox, case viewer, Submitted / Flagged, named download pack, notifications, manager counts.	Clerks process pilot cases without chasing missing photos.
3 Harden	Tier 2 depth from Annex 2 (BYD), second OEM pack at true annex depth, admin pack editor, flag-reason analytics, SSO if not already in.	Group-ready; remaining brands on a configuration timetable.

Phases 1 and 2 can overlap: portal skeleton is built while the capture wizard is in pilot so clerks are not waiting on a second project.

16. Deliverables

- Technician Capture PWA (phone + tablet).
- Warranty Review Portal (desktop).
- Brand Pack v1 — BYD Attachment A, including naming templates.
- Brand Pack v1-common — Tier 1 for all other Booran brands.
- Voice to Tech integration on case notes.
- Admin: users, sites, brands, pack versions.
- Submission pack exporter (zip + summary PDF).
- Short workshop one-pager for technicians (how to start a case).



- Short clerk one-pager (how to review, flag, download).
- Hosting, monitoring and backup in Australia.
- This scope, plus a short test script mapped to Attachment A items.

17. Acceptance test map (BYD seed)

A case is accepted as “complete” for BYD when the following are present and named. This is the operational translation of Attachment A.

Attachment A item	App step	Gate
VIN photo (plate or VDS printout)	1 + 3	Photo + VIN string
Odometer photo – EV / EV+HV	1 + 3	Photo + reading
Front of vehicle photo	1 + 3	Photo accepted
Fault photos – min two (close-up + location)	3	Two accepted photos
Old part serial / barcode (if replaced)	2 + 3	Conditional
New part serial / barcode (if replaced)	2 + 3	Conditional
Before and after repair photos	2 + 3	Conditional
Diagnostic evidence – VDS / DTC / software	2 + 3	Conditional
Video .mp4 for noise / operational faults	2 + 3	Conditional
Tier 2 extras by fault type	2 + 4	Conditional
Header: date, RO, technician, dealer, VIN, odo, claim no.	0 + 1 + user	Always
Naming convention on all files	Submit / export	Always

Portal acceptance: a clerk can open that case, replay media, read Voice to Tech notes, mark Submitted, or flag a specific item and have the technician returned only to that item.

18. Risks and mitigations

Risk	Mitigation
Technicians treat the app as optional and keep shooting an ad-hoc camera roll.	Make it faster than the camera roll: VIN scan, auto-name, no later sorting. Manager dashboard shows who is still bypassing.
Workshop network drops mid-job.	On-device draft and queued upload. Case visible to clerk as Uploading, not lost.
BYD Annex 2 not supplied at kickoff.	Ship category-level Tier 2 plus Tier 1 hard gates. Deepen shots when the annex arrives — configuration, not a rebuild.
Voice quality in a noisy workshop.	Reuse Voice to Tech as-is; keep audio on file; keyboard fallback. Upgrade the model only if pilot transcripts fail.
OEM changes a checklist.	Brand Pack versions. In-flight cases stay on the pack they started.
Clerks still re-name files by hand.	Exporter uses the OEM pattern as the actual filename. Training one-pager shows “download pack > attach to DMS” as the only path.



19. Open items for Booran to confirm

- Pilot rooftop(s) and pilot brand sequence (recommended: one BYD site + one multi-brand site).
- Whether Annex 2 can be released to OmniSuiteAI under the existing NDA for structuring as extra shots.
- DMS name(s) in use per franchise (for Phase 2 RO prefill only — not v1 write-back).
- Preferred identity source (Microsoft 365 / Google / existing Good Showroom accounts).
- Shared workshop tablets vs personal work phones.
- Who holds the Warranty Clerk role at group vs site level.
- Any additional OEM checklists already in circulation (Hyundai, Kia, MG, Chery) that should be transcribed into Brand Packs in Phase 3.

20. Document control

Version	Date	Notes
0.1	3 Sep 2026	Internal outline from BYD-WB-2602-02 Attachment A and Booran multi-brand requirement.
1.0	3 Sep 2026	Draft scope issued for Booran / OmniSuiteAI review. No commercial schedule attached.

SCOPE NOTE

Positioning

This is a Good Showroom aftersales module: capture in the workshop, review in the office, evidence that survives an OEM audit. It does not replace the OEM warranty portal. It stops incomplete packs ever being the reason a claim is delayed or returned.

Shaun Sumaru

Director | OmniSuiteAI Pty Ltd

info@omnisuiteai.com | +61 0499 918 523 | www.omnisuiteai.com