

# **Arduino installation Guide**

• Download the arduino software from <a href="https://www.arduino.cc">https://www.arduino.cc</a>




• Navigate to Softwares in the home page:




• Select arduino ide 1.8.19

And choose windows win7 and newer



• Next, click on just download




• Once done open the downloaded file.


# Click on I agree




#### Click on Next



#### Click on **Install**



#### Click on close.



# Adding board manager:

- 1. Open the arduino application.
- 2. Click on file.


```
sketch_oct10a | Arduino 1.8.19
File Edit Sketch Tools Help

sketch_oct10a

void setup() {
    // put your setup code here, to run once:
}


void loop() {
    // put your main code here, to run repeatedly:
}
```

3. Click on preferences.




# https://arduino.esp8266.com/stable/package\_esp8266com\_index.json

4. Paste the given url in the additional board managers urls.




### 5. Click ok.


# 6. Goto tools.




7. Click on board and next click on board manager.



8. Search for esp8266 and click on install.





9. Click on close.