## 'BASE 15X400X1046

```
BG ID="P1000" SIDE=0 CRN="1" X=6 Y=32 Z=0 DP=12 DIA=6
BG ID="P1010" SIDE=0 CRN="1" X=6 Y=64 Z=0 DP=0 DIA=3.5 THR=YES
BG ID="P1014" SIDE=0 CRN="1" X=6 Y=352 Z=0 DP=0 DIA=3.5 THR=YES
BG ID="P1004" SIDE=0 CRN="1" X=6 Y=384 Z=0 DP=12 DIA=6
BG ID="P1006" SIDE=0 CRN="1" X=70 Y=32 Z=0 DP=0 DIA=5 THR=YES
BG ID="P1008" SIDE=0 CRN="1" X=70 Y=352 Z=0 DP=0 DIA=5 THR=YES
BG ID="P1001" SIDE=0 CRN="1" X=704 Y=352 Z=0 DP=0 DIA=5 THR=YES
BG ID="P1011" SIDE=0 CRN="1" X=704 Y=352 Z=0 DP=0 DIA=3.5 THR=YES
BG ID="P1015" SIDE=0 CRN="1" X=704 Y=352 Z=0 DP=0 DIA=3.5 THR=YES
BG ID="P1005" SIDE=0 CRN="1" X=704 Y=384 Z=0 DP=12 DIA=6
BG ID="P1007" SIDE=0 CRN="1" X=976 Y=32 Z=0 DP=0 DIA=5 THR=YES
BG ID="P1009" SIDE=0 CRN="1" X=976 Y=352 Z=0 DP=0 DIA=5 THR=YES
BG ID="P1009" SIDE=0 CRN="1" X=976 Y=352 Z=0 DP=0 DIA=5 THR=YES
BG ID="P1003" SIDE=0 CRN="1" X=1040 Y=352 Z=0 DP=0 DIA=3.5 THR=YES
BG ID="P1013" SIDE=0 CRN="1" X=1040 Y=352 Z=0 DP=0 DIA=3.5 THR=YES
BG ID="P1012" SIDE=0 CRN="1" X=1040 Y=352 Z=0 DP=0 DIA=3.5 THR=YES
BG ID="P1012" SIDE=0 CRN="1" X=1040 Y=352 Z=0 DP=0 DIA=3.5 THR=YES
BG ID="P1012" SIDE=0 CRN="1" X=1040 Y=352 Z=0 DP=0 DIA=3.5 THR=YES
BG ID="P1012" SIDE=0 CRN="1" X=1040 Y=384 Z=0 DP=12 DIA=6
```