Nordstern Fahrzeugprüfung GmbH

Station München-Nord · Ingolstädter Str. 210 · 80939 München · Officially recognised test organisation

VEHICLE INSPECTION REPORT

Report no. HU-2026-104857
Inspection: 14.10.2026, 10:42

VERSION 1 · INITIAL INSPECTION

MAKE / MODEL	VIN	LICENCE PLATE
Volkswagen Golf VII 1.4 TSI	WVWZZZAUZHW123456	M-JR 4821
FIRST REGISTRATION	**ODOMETER**	**FUEL / EMISSION CLASS**
03/2017	98,412 km	Petrol · Euro 6
OWNER	**ADDRESS**	**INSPECTOR**
Jonas Reiter	Leopoldstraße 112, 80802 München	Dipl.-Ing. Katrin Albers (ID 4471)

FAILED — **Significant defects found.** No inspection sticker issued. The vehicle must be repaired and presented for re-inspection within one month (by 14.11.2026).

NO STICKER ISSUED

DEFECTS FOUND

#	Component	Finding	Classification
1	Brakes, rear axle	Brake pads worn to 1 mm remaining thickness (both sides)	**Significant defect**
2	Engine	Oil leak at oil pan gasket, active dripping observed on the lift	**Significant defect**
3	Lighting	Left low-beam headlamp misaligned	**Minor defect**

MEASUREMENTS

Test	Result	Assessment
Service brake efficiency (rear)	41 %	Below expected value
Emission test	CO idle 0.02 % vol · Lambda 1.001	**Passed**
Tyre tread depth	4.5 – 5.2 mm	**Above legal minimum**

INSPECTOR REMARKS

The vehicle was presented in a clean condition with a complete service booklet. The rear brake pads are at the wear limit and the oil leak at the oil pan gasket now drips actively, unlike at the last inspection. Both must be repaired before the vehicle can pass. The headlamp alignment should be corrected at the same time.

Signed electronically: K. Albers, 14.10.2026 11:05

Nordstern Fahrzeugprüfung GmbH · Station München-Nord

Fictional sample for the ChainBridge demo. Not a real vehicle, person or test organisation.