Nordstern Fahrzeugprüfung GmbH

Station München-Nord · Ingolstädter Str. 210 · 80939 München · Officially recognised test organisation

VEHICLE RE-INSPECTION REPORT

Report no. HU-2026-104857-N1
Re-inspection: 06.11.2026, 09:15

VERSION 2 · RE-INSPECTION AFTER REPAIR

MAKE / MODEL	VIN	LICENCE PLATE
Volkswagen Golf VII 1.4 TSI	WVWZZZAUZHW123456	M-JR 4821
FIRST REGISTRATION	**ODOMETER**	**FUEL / EMISSION CLASS**
03/2017	98,655 km	Petrol · Euro 6
OWNER	**ADDRESS**	**INSPECTOR**
Jonas Reiter	Leopoldstraße 112, 80802 München	Dipl.-Ing. Katrin Albers (ID 4471)

PASSED — **All defects from the initial inspection have been repaired.** Inspection sticker issued. Next periodic inspection due: **10/2028**.

HU 10 / 2028 PASSED

Replaces the result of report HU-2026-104857 (initial inspection of 14.10.2026, result: failed). Repairs carried out by Autohaus Isartal GmbH, München, invoice no. AI-2026-77310 of 03.11.2026.

DEFECTS FROM THE INITIAL INSPECTION

#	Component	Repair	Re-inspection result
1	Brakes, rear axle	Brake pads and discs replaced; new pad thickness 12 mm	**Repaired · OK**
2	Engine	Oil pan gasket replaced, engine oil topped up	**Repaired · no leak**
3	Lighting	Left low-beam headlamp adjusted	**Repaired · OK**

MEASUREMENTS

Test	Result	Assessment
Service brake efficiency (rear)	68 %	**Passed**
Emission test	CO idle 0.02 % vol · Lambda 1.000	**Passed**
Tyre tread depth	4.4 – 5.1 mm	**Above legal minimum**

INSPECTOR REMARKS

The vehicle was re-presented within the deadline. All three defects recorded on 14.10.2026 were checked and found properly repaired. Odometer reading increased by 243 km since the initial inspection, consistent with the drive to and from the workshop. No new defects found.

Signed electronically: K. Albers, 06.11.2026 09:40

Nordstern Fahrzeugprüfung GmbH · Station München-Nord

Fictional sample for the ChainBridge demo. Not a real vehicle, person or test organisation.