

維修建議要正視 檢查維修莫遲疑

Don't Ignore Repair Advice
Inspect and Repair Immediately

聯合辦事處優化處理楼宇漏水檢測程序
Enhancing the Inspection and Testing Procedures
for Handling Water Seepage in Buildings by the Joint Office

- 新增以外線熱感應器以加強偵測熱源水滲漏
(Increase Thermography used to reinforce the screening of source of seepage)



- 業主接獲信後立即發出「建議修葺通知」，要求
在指定時間內自行檢查和維修
(A recommendation letter will be issued to the owner of the upper unit requesting the inspection and repair within a specified time frame)

- 如沒有修葺在指定時間內仍然持續，
聯合辦事處將展開調查，並向上樓單位
業主收短租賠償
(If water seepage persists after the deadline, the joint office will conduct investigation and recover the compensation cost incurred from the owner of the upper unit)



維修建議要正視 檢查維修莫遲疑

Don't Ignore Repair Advice
Inspect and Repair Immediately

聯合辦事處優化處理楼宇漏水檢測程序
Enhancing the Inspection and Testing Procedures
for Handling Water Seepage in Buildings by the Joint Office

- 新增以外線熱感應器以加強偵測熱源水滲漏
(Increase Thermography used to reinforce the screening of source of seepage)

- 業主接獲信後立即發出「建議修葺通知」，要求
在指定時間內自行檢查和維修
(A recommendation letter will be issued to the owner of the upper unit requesting the inspection and repair within a specified time frame)

- 如沒有修葺在指定時間內仍然持續，
聯合辦事處將展開調查，並向上樓單位
業主收短租賠償
(If water seepage persists after the deadline, the joint office will conduct investigation and recover the compensation cost incurred from the owner of the upper unit)



妥善處理漏水問題，是業主應有的責任。
若樓宇出現漏水，業主應先自行安排檢查及
維修，如發現漏水戶和業主結鄰，及早進行修
繕工程。

滲水問題同解決
有商有量好街坊

