

# 維修建議要正視 檢查維修莫遲疑

Don't Ignore Repair Advice  
Inspect and Repair Immediately

聯合辦事處優化處理樓宇滲水檢測程序  
Enhancing the Inspection and Testing Procedures  
for Handling Water Seepage in Buildings by the Joint Office

- 新增以外線熱感應器加強偵測滲水熱源  
(Optional Thermography added to expedite the screening of source of seepage)



- 向土庫單位業主發出「建議修葺通知」，要求  
在指定時間內自行檢查和維修  
A recommendation letter will be issued to the owner of the upper unit requesting the inspection and repair within a specified time frame.

- 如滲水問題在短期區隔內仍然持續，  
聯合辦事處將展開調查，並向土庫單位  
業主收短租賠償。  
If water seepage persists after the deadline, the joint office will conduct investigation and recover the compensation cost incurred from the owner of the upper unit.



## 維修建議要正視 檢查維修莫遲疑

Don't Ignore Repair Advice  
Inspect and Repair Immediately

聯合辦事處優化處理樓宇滲水檢測程序  
Enhancing the Inspection and Testing Procedures  
for Handling Water Seepage in Buildings by the Joint Office

- 新增以外線熱感應器加強偵測滲水熱源  
(Optional Thermography added to expedite the screening of source of seepage)



- 向土庫單位業主發出「建議修葺通知」，要求  
在指定時間內自行檢查和維修  
A recommendation letter will be issued to the owner of the upper unit requesting the inspection and repair within a specified time frame.

- 如滲水問題在短期區隔內仍然持續，  
聯合辦事處將展開調查，並向土庫單位  
業主收短租賠償。  
If water seepage persists after the deadline, the joint office will conduct investigation and recover the compensation cost incurred from the owner of the upper unit.



妥善處理滲水問題，是業主應有的責任。  
新樓宇出現滲水，業主應先自行安排檢查滲水  
原因，如發現難以解決，應立即向屋宇處、及專業行報  
修工程。

滲水問題同解決  
有商有量好街坊

