

Date: 11 January 2017 From: STMicroelectronics

Subject: Version 3.5.3 Release Notes SPWF01S-170111-665d284

## (1)Hiahliaht:

This release mainly includes bug fixes, and new minor features for module tuning

## (2)New Features

- \* Added wifi\_dtim\_period, allowing user to tune miniAP powersave feature
- \* Added wifi\_add\_tim\_ie, allowing miniAP to broadcast traffic information map inside beacons
- \* Added ip\_block\_pings configuration variable, allowing user to avoid automatic reply to ICMP echo requests
- \* Added ip\_dns2 status variable, showing secondary DNS server in use
- \* Added Random Transaction ID to DNS question
- \* Added CRC check to configuration variables
- \* Added WIND:79 to signal an automatic factory reset, due to CRC failure detection at startup
- \* Added possibility for miniAP to accept powersaving STAs. DTIM was fixed to 1 (frames not stored)

## (3)Bug fixes

- \* Fixed input\_demo timeout signal on resulting HTML page
- \* Fixed garbage characters on UART after WIND:2 when low baudrates were used
- \* Fixed DNS TimeToLive issue (Ref: #36899 LWIP bug)
- \* Increased DNS client buffer size. Now big payload, up to 512 bytes in size, are managed

## (4)Backward compatibility changes

\* Updated configuration variables (WIND:73 displayed)