Maintenance Procedure No. P231

Page 1 of 1

TASK DESCRIPTION			
CHECK ALL 575 VOLT AC TRAINLINE RECEPTACLES FOR GROUNDS OR SHORTS.			
BUILDER'S OR VENDOR'S MAINTENANCE INSTRUCTIONS			
Caterpillar Master Inspection Data Book			
SPECIAL TOOLS REQUIRED:			
RELATED MAINTENANCE PROCEDURES MODIFICATIONS, POINTERS, ETC.			
SAFETY PRECAUTIONS:			
CONTRACTOR TO ASSUME RESPONSIBILITY FOR SAFETY RULES AND COMPLIANCE.			
PREPARATION:			

PROCEDURE

- 1 Using a digital voltmeter set on the 20-megohm scale; check the resistance to ground for each socket on each receptacle. A reading of 1 Meg ohm or more is considered satisfactory.
- 2 Check the resistance between each socket at each receptacle. A reading of 1 Meg ohm or more is considered satisfactory.

DATE OF FIRST ISSUE	May 1997	AUTHORIZED BY:
REVISION 0		TITLE: Manager, Rail Equipment