Inspection Report: RPT-2025-09-29-9411F5

Inspected Item:

damage_type: Crack severity: Critical

action_required: Immediate Replacement

inspector_name: Test inspector_id: INSP-0001 vendor: Railtech industries

batch: BATCH-4820 location: jaipur rid: RID003

timestamp: 2025-09-29T19:31:40.707165

photo_filename: scaled_29446e28-8988-4821-b4dc-9c96a4459d233479137291320727159.jpg

Al Analysis:

condition_score: 20

predicted_failure_risk: Immediate risk of failure; replacement required

vendor_score: No vendor alert

Work Order:

priority_level: Critical

action: Immediate Replacement spare_part_sku: BOLT-M10-A

assigned_to: Jaipur Maintenance Division

status: Pending

Supervisor Approval:

Supervisor Signature:

Date: 2025-09-29