

Address(H) Code(H) Assembly Line

Address(H)	Code(H)	Assembly Line
0000		org 0
0000	1FBD	add R ₄ , R ₄ 000 1111 0111 0111
0002	F03D003D	mov R ₄ , #41 1111 0000 0000 1111 0100 0000 0000 1111 0101
0004	1FBC	loop: add R ₄ , R ₄ 000 1111 0111 0111
000A	8F3C0006	mov R ₄ , R ₄ , loop 1000 1111 0000 1111 0000 0000 0000 0110
000C	F0BC0001	sub R ₄ , #1 1111 0000 1011 1100 0000 0000 0000 0000
0010	9F3C0006	mov loop, R ₄ , R ₄ 1000 1111 0000 1111 0000 0000 0000 0110
0014	5F3C	xor R ₄ , R ₄ 0101 1111 0000 1111 0111
0018	F0BD0001	sub R ₄ , #1 1111 0000 1011 1100 0000 0000 0000 0001
001A	BF3D0006	jne R ₄ , R ₄ , loop 1011 1111 0000 1111 0100 0000 0000 0110
001E	E03F0000	call R ₀ , 0(R ₄) 1110 0000 0000 1111 1111 0000 0000 0000
		end