

Address(H) Code(H) Assembly Line

0000		org 0	
0007	90020	load (pointer_1)	1001 0000 0000 0101 0101
000D	50040	store sum	0011 0000 0000 0110 0110
000A	90029	load (pointer_2)	1001 0000 0000 0101 1001
000F	50040	add sum	0100 0000 0000 0110 0101
0015	A0020	store (pointer_3)	1010 0000 0000 0101 1101
0019	50020	load pointer_1	0010 0000 0000 0101 0101
001E	10005	add #4	0001 0000 0000 0000 0100
0023	50020	store pointer_1	0011 0000 0000 0101 0101
002A	10005	add #4	0001 0000 0000 0000 0100
0030	50029	store pointer_2	0011 0000 0000 0101 1001
0035	10005	add #4	0001 0000 0000 0000 0100

Address(H) Code(H) Assembly Line

003V	Y002D	store pointer_3 0011 0000 0000 0101:1101
003C	Y004	load counter 0010 0000 0000 0110 0001
00F1	1FFFF	add #-1 0001 1111 1111 1111 (
00F4	Y0041	store counter 0011 0000 0000 0110 0001
00FB	D0000	jnz loop 1101 0000 0000 0000 0000
0020	B1234	j OS-return-addr 1011 0001 0010 0011 0100 1234 آدرس فرستادن
0022		pointer_1: dw array i ;
0029		pointer_2: dw array+4 ;
002D		pointer_3: dw array+8 ;
0041		counter: dw 18
004D		sum: dw ? ;
0049		array: dw 0, 1, 18 dup(?) ;
		end