

STATE MACHINE		
name	led_fsm	
clock	clk	posedge
reset_signal	reset	posedge
reset_state	state0	
INPUTS		
b0	'0'	
clk	'0'	
reset	'0'	
OUTPUTS		
L[2:0]	"000"	regdp
STATES		
L[2:0]	"000"	output
TRANSITIONS		
equation	1	def_type

