

```

clc;
clear;
close all;

fp = 1000;
fs = 4000;
N = 50;
wc = fp/(fs/2);

b_hamm = fir1(N, wc, 'low', hamming(N+1));
disp('--- Hamming Window Coefficients ---');

```

```

--- Hamming Window Coefficients ---

```

```

disp(b_hamm');

```

```

0.0010
0
-0.0013
0
0.0021
0
-0.0034
0
0.0055
0
-0.0084
0
0.0125
0
-0.0181
0
0.0260
0
-0.0379
0
0.0580
0
-0.1026
0
0.3168
0.4995
0.3168
0
-0.1026
0
0.0580
0
-0.0379
0
0.0260
0
-0.0181
0
0.0125
0
-0.0084
0
0.0055

```

```
0  
-0.0034  
0  
0.0021  
0  
-0.0013  
0  
0.0010
```

```
figure;  
freqz(b_hamm,1);  
title('Low-pass FIR using Hamming Window');
```

