

```

clc; clear; close all;

fp = 1000;
fs = 8000;
N = 50;
wc = fp/(fs/2);

b_hamm = fir1(N, wc, 'high', hamming(N+1));

disp('--- High-Pass Coefficients (Hamming Window) ---');

```

```

--- High-Pass Coefficients (Hamming Window) ---

```

```

disp(b_hamm');

```

```

-0.0007
  0
 0.0009
 0.0016
 0.0015
  0
-0.0024
-0.0044
-0.0039
  0
 0.0060
 0.0103
 0.0088
  0
-0.0128
-0.0217
-0.0184
  0
 0.0268
 0.0464
 0.0410
  0
-0.0725
-0.1567
-0.2240
 0.7493
-0.2240
-0.1567
-0.0725
  0
 0.0410
 0.0464
 0.0268
  0
-0.0184
-0.0217
-0.0128
  0
 0.0088
 0.0103
 0.0060
  0
-0.0039
-0.0044
-0.0024
  0

```

```
0.0015
0.0016
0.0009
0
-0.0007
```

```
figure;
freqz(b_hamm,1);
title('High-pass FIR using Hamming Window');
title('High-pass FIR using Hanning Window');
```

