

■ INCORRECT SPECIFICATIONS (Defective Copy)

Based on Sheet A100 — CD Sample Project | Project No: 20-514

Contains intentional defects — Mix of Obvious & Subtle — For AI Conflict Detection Testing

Doc No:	SPEC-A100-20514-DEFECTIVE	Date:	November 13, 2020
Project:	CD Sample Project — Residential Renovation	Sheet Ref:	A100
Prepared By:	Transforming Architecture	License:	Architect #13662 — Maryland
Version:	DEFECTIVE — For AI Testing Only	Total Defects:	15 (8 Obvious + 7 Subtle)

SECTION 09300 — ROOM FINISH SCHEDULE ■ Contains Defects

Room Name	Floor	Walls	Ceiling	Remarks
Bath Room 2	Ceramic Tile	Painted Gyp. Bd.	Painted Gyp. Bd.	
Bedroom 2	LVT	Painted Gyp. Bd.	Painted Gyp. Bd.	
Bedroom 3	Carpet	Painted Gyp. Bd.	Painted Gyp. Bd.	
Entertainment Area	LVT	Painted Gyp. Bd.	Painted Gyp. Bd.	
Storage (Basement)	LVT ■ WRONG — should be Unfinished]	Unfinished	Unfinished	
Sump Closet	Concrete	Unfinished	Unfinished	
Master Bath	Ceramic Tile	Painted Gyp. Bd.	Painted Gyp. Bd.	
Master Bedroom	Carpet	Painted Gyp. Bd.	Painted Gyp. Bd.	
Living Room	LVT	Painted Gyp. Bd.	Painted Gyp. Bd.	
Dining Room	Carpet ■ WRONG — should be LVT]	Painted Gyp. Bd.	Painted Gyp. Bd.	
Kitchen	LVT	Painted Gyp. Bd.	Painted Gyp. Bd.	Tile backsplash at counters
Craft Room	LVT	Painted Gyp. Bd.	Painted Gyp. Bd.	Quartz countertop
Pantry	LVT	Painted Gyp. Bd.	Bead Board	
Laundry / Mudroom	Ceramic Tile	Painted Gyp. Bd.	Painted Gyp. Bd.	
Garage	LVT ■ WRONG — should be Concrete]	Painted Gyp. Bd.	Gyp. Bd.	5/8" fire-rated gypsum bd.
Sunroom	LVT	Bead Board	Bead Board	6" white baseboard trim

SECTION 08100 — DOOR SCHEDULE ■ Contains Defects

No.	Size	Int/Ext	Saddle	Remarks
101	3/0x6/8	EXT	YES	8-Lite Entry Door w/ Built-in Blinds & Storm Door
102	2/8x6/8	INT	NO	Single Door — 3 Panel U.N.O.

103	3/0x6/8	INT	NO	Single Door
104	1/6x3/0 ■ WRONG — should be 2/8x6/8]	INT	NO	Single Door
105	3/0x6/8	INT	NO	Single Door
106	2/4x6/8	INT	NO	Single Door
107	2/6x6/8	INT	NO	Single Door
108	2/0x6/8	INT	NO	Single Door
109	(2)2/4x6/8	INT	NO	Double Bifold Door
110	(2)4/0x6/8	INT	NO	Double Bifold Door
111	3/0x6/8	INT	YES	Pocket Door
112	(2)3/0x6/8 ■ WRONG — should be (2)2/0x6/8]	INT	NO	Double Barn Door
113	(2)3/0x6/8	INT	NO	Double Barn Door
114	(2)2/0x6/8	EXT	YES	Double Storm Door — w/ Sliding Screen
115	3/0x6/8	EXT	NO	Storm Door — w/ Sliding Screen
116	3/0x6/8	EXT	YES	Storm Door
117	(2)1/3x6/8	EXT	YES	Double Door
118	3/0x6/8	EXT	YES	15-Lite Entry Door
119	3/0x6/8	INT	NO	Single Door — Fire Rated 1HR
120	(2)2/3x6/8	INT	NO	Double Door
121	8/0x7/0 ■ WRONG — should be 9/0x7/0]	EXT	NO	Garage Door — Clopay CD13
122	9/0x7/0	EXT	NO	Garage Door — Clopay CD13
125	3/0x6/8	EXT	YES	Thermatru CCA260-SDL Classic Craft American
ATT	20x54	INT	NO	Aluminum Attic Ladder

SECTION 08500 — WINDOW SCHEDULE ■ Contains Defects

■ DEFECT: U-Factor listed below as 0.35 — INCORRECT. Correct value per A100: MAX. U = 0.31

Label	Mat.	Size	Operation	Remarks
A	NYL	2/6x4/0 ■ WRONG — should be 3/0x5/0, egress req.]	Double Hung	Egress Window — ProFinish 600
B	NYL	Varies	Double Hung	Egress Window — ProFinish 600
C	NYL	(2)2/4x5/0	Casement	ProFinish 600 Series
D	NYL	2/0x3/0	Casement	ProFinish 600 Series
E	NYL	(3)2/0x3/0	Casement	ProFinish 600 Series
F	NYL	(2)2/0x4/4	Casement	ProFinish 600 Series
G	NYL	4/0x1/0	Transom	Fixed Transom

H	NYL	1/0x4/6 [■ WRONG — should be 2/0x4/6]	Casement	ProFinish 600 Series
J	NYL	2/0x1/0	Transom	Fixed Transom
K	EX.	Varies	Casement	Replace existing w/ Sliding Window
1/6x3/0	NYL	1/6x3/0	Fixed	Sidelight

SECTION 06100 — HEADER SCHEDULE U.N.O. ■ Contains Defects

Opening Size	Header Size	Material	Remarks
Openings up to 3'-0"	(2) 1.75x11.875 1.9E Microlam [■ WRONG — should be (2) 2x10]	Engineered LVL	Oversized — structural issue
Openings > 3'-0" to 6'-0"	(2) 1.75x9.50 1.9E Microlam	Engineered LVL	Correct
Openings > 6'-0" to 8'-0"	(2) 1.75x11.875 1.5E Microlam	Engineered LVL	Large span header

DEFECT ANSWER KEY — 15 Total | ■ Obvious: 8 | ■ Subtle: 7

ID	Section	Item	Defective Value	Correct Value	Visibility	Severity
R-01	09300	Bedroom 2 Floor	LVT	Carpet	SUBTLE	MED
R-02	09300	Storage Floor	LVT [■ ■]	Unfinished	OBVIOUS	HIGH
R-03	09300	Master Bath Walls	Painted Gyp. Bd.	Ceramic Tile	SUBTLE	HIGH
R-04	09300	Dining Room Floor	Carpet [■ ■]	LVT	OBVIOUS	MED
R-05	09300	Pantry Ceiling	Bead Board	Painted Gyp. Bd.	SUBTLE	LOW
R-06	09300	Garage Floor	LVT [■ ■]	Concrete	OBVIOUS	HIGH
D-01	08100	Door 102 Size	2/8x6/8	3/0x6/8	SUBTLE	MED
D-02	08100	Door 104 Size	1/6x3/0 [■ ■]	2/8x6/8	OBVIOUS	HIGH
D-03	08100	Door 106 Size	2/4x6/8	2/6x6/8	SUBTLE	LOW
D-04	08100	Door 109 Size	(2)2/4x6/8	(2)2/6x6/8	SUBTLE	MED
D-05	08100	Door 112 Size	(2)3/0x6/8 [■ ■]	(2)2/0x6/8	OBVIOUS	HIGH
D-06	08100	Door 121 Size	8/0x7/0 [■ ■]	9/0x7/0	OBVIOUS	HIGH
D-07	08100	Attic Ladder Size	20x54	22.2x54	SUBTLE	LOW
W-01	08500	Window A Size	2/6x4/0 [■ ■]	3/0x5/0	OBVIOUS	HIGH
W-02	08500	Window C Size	(2)2/4x5/0	(2)2/6x5/0	SUBTLE	MED
W-03	08500	Window F Height	(2)2/0x4/4	(2)2/0x4/6	SUBTLE	LOW
W-04	08500	Window H Size	1/0x4/6 [■ ■]	2/0x4/6	OBVIOUS	HIGH
W-05	08500	Window K Operation	Casement	Slider	SUBTLE	MED
H-01	06100	Header ≤3'	LVL 11.875 [■ ■]	(2) 2x10 Timber	OBVIOUS	HIGH
H-02	06100	Header >6' Grade	1.5E Microlam	1.9E Microlam	SUBTLE	HIGH