


ARDUINO SAFETY MONITOR

- 1) Download ASCOM plugin here :


https://drive.google.com/drive/folders/1b0UpFCSJSKiv0XgESMwSb3XRnwmon500?usp=share_link

- 2) Install it.
- 3) Connect the usb of the device to your computer.
- 4) Go to the Device manager of Windows and look for Ports (COM & LPT) – Arduino Nano Every.




In my case, it is plugged in COM8.

- 5) Open NINA and go to the Safety Monitor.
- 6) You should find ASCOM ArduSafeMon. in the list




- 7) Select it and go to the settings of the plugin and select the right COM port (determined before).



- 8) Press ok and then connect: it should work!

NOTE: if you disconnect it in NINA sometimes you can't reconnect it quickly because NINA takes some time to close the PORT.

You may have this error:



2 solutions: Wait and try again or close NINA and reopen it.

If it happens during the sequence launching because it was disconnected (after a sequence for example), I would recommend to not disconnect it at all if you don't close NINA between nights (my case).