Photo Guide

Print quality

When including photos to demonstrate the print quality of 3D printed parts, make sure that any areas including text and small detailed elements are displayed clearly. Make sure there is enough contrast between the text and the surface it is printed on.

Good Example:

Bad Example:

Part photos

When including photos and images for parts, make sure that the

Good Example:

A1	LipSync Hub PCB	QTY 1	A4	Resistor R2/R3/R4 68 Ω, ¼ W, Through hole	QTY 3

Bad Example:

Assembly photos

Good Example:

Bad Example:

Device photos

Good Example:

Bad Example: