

































Schrittmotor	Wicklung	Farbe	Buchse 4P	Stecker 9P		Sensor Notaus
Α	1	SW	1	6		
С	ı	gn	2	7		
В	2	rt	3	8		
D	2	bl	4	9		
GND	Endsrtop XYZ			1	Sensor	1
Signal	Lilusitop X12			3	3611301	3
(+V) [12V]				5		
12V →					NotAssa	4
12V ←					NotAus	5