SAMPLE REPORT — Demonstration data only / تقرير توضيحي — بيانات تجريبية فقط

BURHAN برهان

Version 1

7c4b5335-017e-438b-974f-a5a66ef8c9f2

Construction inspection report

SAMPLE · QA · First floor wall

Project
SAMPLE / مثال توضيحي · QA · Riyadh Site

Location
Block A / Floor 1 / Wall 04

Inspector
QA Inspector

Issued
21/10/2026, 01:49:31

Inspection scope

manual · preconstruction · completed

Confirmed findings: 1 | Unreviewed candidates: 0 | Dismissed candidates: 0

Findings

1. Visible wall damage

Review status: **confirmed** · Issue status: open · Inspector priority: high

Inspector notes
QA evidence collected during browser smoke.

Corrective action
Repair and inspect again.

Inspection checks

visual	not checked
evidence	not checked
Authority-approved permit	not checked
signed coordinated drawings	not checked

project occupancy and construction classification	not checked

Method and limitations

Local experimental visual models assist an inspector. Misses and false alerts are documented. Model confidence is not physical severity. An empty detection is not a pass. Strength, hidden defects, moisture content, dimensions and code compliance require appropriate evidence and qualified review.

SAMPLE — Browser workflow demonstration. No real site inspection or camera detection was performed. مثال توضيحي لا يمثل فحصًا حقيقيًا للموقع.