All System Diagnostic Report

The Report is created by Ediag

Vehicle Information

SN:9TBC29728913
Make:TOYOTA
Model:Camry
Year:2007
VIN:4T1BE46K17U046638
Mileage:0 Miles
Test Time:08/05/2026 22:50:36

Inspection Result

SRS-Supplemental Inflatable Restraint System 8 problems exist

1.B1811 Open in Driver's Squib (Dual Stage - 2nd Step) Circuit

2.B1650 Occupant Classification System Malfunction

3.B1653 Driver Side Seat Position Sensor

4.B1655 Seat Belt Buckle Switch (Driver Seat Side)

5.B1660 Passenger Seat Airbag Active Mode Indicator

6.B1811 Open in Driver's Squib (Dual Stage - 2nd Step) Circuit

7.B1821 Open in Side Squib (Driver Seat Side) Circuit

8.B1826 Open in Side Squib (Passenger Seat Side) Circuit