AI Damage Inspection Report

Generated by CrackEye System

Detection Output

Location Details

Area: 18.931845, 73.162265

Latitude: None

Longitude: None

Damage Analysis

Type: crack

Category: infrastructure

Severity: medium

Confidence: 86.0%

Geometry Metrics

Mask Area: 1847.9

BBox Area: 313476

Risk Assessment

Risk Score: 6.59

Priority: medium

Traffic Impact: high

Recommended Action

Action: crack sealing

Method: injection sealing

Material: epoxy resin

Estimated Cost: ■110.87

Time Required: 2 hrs