AI Damage Inspection Report

Generated by CrackEye System

Detection Output

Location Details

Area: 18.931847, 73.162222

Latitude: None

Longitude: None

Damage Analysis

Type: crack

Category: infrastructure

Severity: low

Confidence: 70.0%

Geometry Metrics

Mask Area: 951.8000000000001

BBox Area: 85902

Risk Assessment

Risk Score: 2.67

Priority: low

Traffic Impact: high

Recommended Action

Action: crack sealing

Method: injection sealing

Material: epoxy resin

Estimated Cost: ■57.11

Time Required: 2 hrs