

In the non ip usage report there were less combinational LUTs being used, less block memory bits being used, and a smaller total fan-out. The non ip and ip used almost the exact same number of logic registers, only having a difference of one. Although the non ip version had less combinational LUTs it did use some bigger input LUTs. These differences are all caused by the different uses of logic to ultimately complete the same thing.