Static Meter   Static Meter   Static Meter   Static Meter   Make: Test CT Manufacturer   Serial No: Serial No: Serial No: SN123456789   Meter Constant 100/5   Serial No: SN123456789   Meter Constant 1000   Class: 1.0   Meter Current: 5A   Meter	Report No: OPT-20		Branch:	GAL			timized Test	A/C No:	12345		Contract Der 1200:	
Make:   Test CT Manufacturer   Ratio:   100/5   Serial No. SN123456789   Meter Constant 1000   Class:   1.0   Meter Current: 5A   Meter Current: 5A   Meter Voltage: 230V	Date of Test 20025-01-15 CSC: TEST Substation N					station N	B004'	Reason:	routine Request ID: REQ		EQ001	
Ratio   100/5	<b>Current Transfor</b>	mer					Static Meter					
Meter Constant 1000   Class: 1.0   Meter Current: 5A   Meter Voltage: 230V			er									
Class: 1.0   Meter Course: 5A   Meter Voltage: 230V	Ratio: 100/	/5							9			
Meter Current: 5A   Meter Voltage: 230V												
Meter Voltage: 230V												
Physical Condition of the Meter:   Good   Phases   R   Y   B												
Phases   R   Y   B							•		notar Manufactur	PARIAL NA. TENITON	142245	
CT Ratio:   100/5   Voltage(V)   230.5   231.2   229.8							i ilases	viake. Test I				
Meter Ratio:   100/5   Current(A) Primary   100.5   95.2   105.8		of the Meter:								-		
Multiplying Factor:         1         Current(A) Secondary         5.025         4.76         5.29           Connection of Meter Elements:         3ph4w         Phase Sequence:         Correct           CT Earthing:         Yes         %Error as Found:         0.5           %Error as Left:         0.2           Measurings         Total         Rate A         Rate B         Rate C           Energy kWh         1000.123         50.456         300.789         10.123         350.456         15.789         350.123         25.456           Demand kVA         500.123         25.456         150.789         5.123         175.456         8.789         175.123         12.456           R.Energy kVArh         200.123         10.456         60.789         2.123         70.456         3.789         70.123         5.456           Comments:         This is a comprehensive test report for the optimized PDF layout. The layout should now use the full A4 space efficiently with minimized gaps and maximized content density. All tables should be properly positioned with the Phases table on the right side of the Check section and the Measurings table spanning the full width below.							0 ( )					
Connection of Meter Elements: 3ph4w  Phase Sequence: Correct  CT Earthing: Yes  %Error as Found: 0.5  %Error as Left: 0.2  Measurings Total Rate A Rate B Rate C  Import Export Import Export Import Export  Energy kWh 1000.123 50.456 300.789 10.123 350.456 15.789 350.123 25.456  Demand kVA 500.123 25.456 150.789 5.123 175.456 8.789 175.123 12.456  R.Energy kVArh 200.123 10.456 60.789 2.123 70.456 3.789 70.123 5.456  Average Power Factor 0.950  Comments: This is a comprehensive test report for the optimized PDF layout. The layout should now use the full A4 space efficiently with minimized gaps and maximized content density. All tables should be properly positioned with the Phases table on the right side of the Check section and the Measurings table spanning the full width below.												
Phase Sequence:   Correct	1,70	-					Current(A) Seco	ndary	5.025	4.76	5.29	
Yes		r Elements:		<u> </u>			_					
Measurings         Total         Rate A         Rate B         Rate C           Import         Export         Import         Export         Import         Export           Energy kWh         1000.123         50.456         300.789         10.123         350.456         15.789         350.123         25.456           Demand kVA         500.123         25.456         150.789         5.123         175.456         8.789         175.123         12.456           R.Energy kVArh         200.123         10.456         60.789         2.123         70.456         3.789         70.123         5.456           Average Power Factor         0.950         0							_					
Measurings   Total   Rate A   Rate B   Rate C	•						$\dashv$					
Name							$\dashv$					
Import Export Import Export Import Export Import Export Import Export Energy kWh 1000.123 50.456 300.789 10.123 350.456 15.789 350.123 25.456  Demand kVA 500.123 25.456 150.789 5.123 175.456 8.789 175.123 12.456  R.Energy kVArh 200.123 10.456 60.789 2.123 70.456 3.789 70.123 5.456  Average Power Factor 0.950 70.123 5.456  This is a comprehensive test report for the optimized PDF layout. The layout should now use the full A4 space efficiently with minimized gaps and maximized content density. All tables should be properly positioned with the Phases table on the right side of the Check section and the Measurings table spanning the full width below.					T	Dada A			ada D		4- 0	
Energy kWh 1000.123 50.456 300.789 10.123 350.456 15.789 350.123 25.456  Demand kVA 500.123 25.456 150.789 5.123 175.456 8.789 175.123 12.456  R. Energy kVArh 200.123 10.456 60.789 2.123 70.456 3.789 70.123 5.456  Average Power Factor 0.950 70.123 5.456  Comments: This is a comprehensive test report for the optimized PDF layout. The layout should now use the full A4 space efficiently with minimized gaps and maximized content density. All tables should be properly positioned with the Phases table on the right side of the Check section and the Measurings table spanning the full width below.	weasurings	Import	Iotai	Evnort			Export					
Demand kVA 500.123 25.456 150.789 5.123 175.456 8.789 175.123 12.456  R.Energy kVArh 200.123 10.456 60.789 2.123 70.456 3.789 70.123 5.456  Average Power Factor 0.950	Energy kWh				·							
Average Power Factor 0.950 0.9												
Comments: This is a comprehensive test report for the optimized PDF layout. The layout should now use the full A4 space efficiently with minimized gaps and maximized content density. All tables should be properly positioned with the Phases table on the right side of the Check section and the Measurings table spanning the full width below.	R.Energy kVArh	200.123		10.456	60.789		2.123	70.456	3.789	70.123	5.456	
maximized content density. All tables should be properly positioned with the Phases table on the right side of the Check section and the  Measurings table spanning the full width below.	Average Power Factor	0.950										
maximized content density. All tables should be properly positioned with the Phases table on the right side of the Check section and the  Measurings table spanning the full width below.	Comments: This	s is a comprehe	ensive tes	t report for t	he optimized Pl	OF lavout.	The lavout should	d now use	the full A4 space	e efficiently with minir	mized gaps and	
Technical Officer Chief Engineer-SGS	Mea	asurings table s	panning	the full width	h below.							
Technical Officer							Chief Engineer	909				
							Criter Engineer-	303				

This is a computer-generated document.