




NOTE

1. DEBURR ALL UNSPECIFIED EDGES TO C0.3 - C0.4
2. SURFACE TO BE ANODIZED, WHITE
3. DIMENSIONS AFTER ANODIZING
4. INSERT HELICOILS
5. CLEAN PART WITH ISOPROPYL ALCOHOL
6. USE NAMEKAWA HEIGH PLATE(A5052-H112) MATERIAL OR EQUIVALENT
7. INTERPRET DRAWING, DIMENSION, TOLERANCE AND SYMBOL PER JIS.