

INFORMATION ON RISKS AND REGULATIONS **BEHAVIORAL GUIDELINES FOR EXTERNAL PERSONNEL**

Single Interference Risk Assessment Document Cooperation and
coordination for the implementation of prevention and protection measures
pursuant to art. 26, paragraph 3, of Legislative Decree 30 April 2008 no. 81, as amended by Legislative Decree 106/2009

entrusting of works, services and supplies to contractors or self-
employed workers within the company

Implementation of Article 1 of Law No. 123 of 3 August 2007
on health and safety in the workplace

Companies

METALLURGICA BRESCIANA SpA

Metallurgica Bresciana Spa

OPTOTEC SpA



Production unit

Via Guglielmo Marconi, 31 - 25020 Dello (BS)

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 2 of 17

PREMISE

This notice, in compliance with the obligations set forth in Article 26 of Legislative Decree 81/2008, contains information and defines the rules of conduct to be followed by all companies or independent contractors who, for various reasons, access the Metallurgica Bresciana SpA and OPTOTEC SpA production facilities located at Via Guglielmo Marconi, 31 in the municipality of Dello (BS), for the purpose of carrying out work, services, or supplies, in order to ensure the protection of the environment and the health and safety of people.

SCOPE OF APPLICATION

This policy applies to all activities carried out at the facility located at Via Guglielmo Marconi, 31 in the municipality of Dello (BS) by suppliers, contractors, consultants, and other personnel not belonging to Metallurgica Bresciana SpA or Optotec SpA, such as hired or temporary staff. It also applies to visitors.

With regard to procurement or work contracts, this document also constitutes part of the joint Risk Assessment Document, in compliance with the provisions of Article 26 of Legislative Decree 81/2008.

METHOD OF DISSEMINATION TO INTERESTED PARTIES

The information herein will be disseminated by hand delivery, email, or registered mail to the management of the companies whose employees will be working within the Metallurgica Bresciana SpA and Optotec SpA plants.

The management of the companies involved, in turn, must inform their staff in order to ensure understanding, compliance, and implementation of these rules of conduct.

COORDINATION MEETING

Where applicable, companies carrying out subcontracted work must arrange a preliminary meeting on-site before entering the plant. This meeting is intended to provide the necessary information to the management of Metallurgica Bresciana SpA and/or Optotec SpA and, at the same time, acquire the information needed to ensure safe coordination of the work.

This information can be transmitted using the DUVRI "Joint Interference Risk Assessment Document" form, duly completed and signed in the relevant sections.

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 3 of 17

DESCRIPTION OF THE CONTEXT

Metallurgica Bresciana SpA is an industrial company in the rubber-plastic sector that deals with the production of special electrical and fibre optic cables based on the specific requests of its customers.

The processes are carried out through several successive phases using the machinery and production lines present at its production unit at Via Guglielmo Marconi, 31 in the municipality of Dello, made up of several warehouses/factory buildings built in different eras.

The Metallurgica Bresciana plant also includes the headquarters of its partner company Optotec SpA, which has a production department and a tensile warehouse in Dello.

The total area occupied by the company is approximately 62,000 m², part of which is not yet built on and is intended for future expansion.

Shed 1 includes the office and service building, the cable production department, the irradiation department (Dynamitron), and the production areas granted for use to the partner company Optotec Spa


Shed 2 includes the raw materials warehouse, the cable production department, the laboratories, the service rooms and the changing rooms.

Shed 3 includes the raw materials warehouse, the cable production department, the semi-finished product processing cells, the raw materials storage cells, and the logistics and production offices.

Shed 4 includes the fiber optic department with the fiber optic cable insulation/sheathing, coloring and stranding lines, the fiber optic warehouse, the fiber coloring department, the electrical cabin, the service rooms and the changing rooms.

Shed 5 includes the packaging and shipping department, the logistics offices and the loading/unloading bays.

The OPT warehouse is a tensile structure used as a warehouse for the exclusive use of the partner company Optotec SpA



General plan of the production unit, identifying the various buildings and areas used by the Metallurgica Bresciana and Optotec companies.



- Extrusion lines; • Stranding machines; • Screening machines, winding machines; • Spiraling machines, taping machines; • Tape and/or wire armouring machines; • Refinishing and packaging lines; • Dynamytron cable irradiation system; • Optical fibre colouring; • Workshop machine tools for maintenance; • Electric forklifts, jib cranes for handling; • Technical-administrative offices; • Technical laboratories; • Electrical cabin, boiler room, water system, refrigerated cell, air conditioning system.

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 5 of 17

WORKING PHASES OF THE TECHNOLOGICAL CYCLE

- Design of electrical cables according to the client's specific requests; • Procurement of raw materials consisting mainly of: o metal conductive wires of various types and thicknesses; o textile fibers; o optical fiber wires; o various types of plastic materials in granules for extrusion; o inks, solvents for markers; o accessory materials, tapes, etc. • Stranding/coiling/stranding of elementary wires; •

Extrusion for the creation of insulation/sheathing/tubes for

metal and optical fiber conductors; • Coloring of optical fibers; • Stranding, Spiraling, Shielding, Taping; •

Possible irradiation treatment of

the cable coating with electron beam using a Dynamitron

system; • Product quality testing and controls; • Rewinding; • Packaging and wrapping of finished product reels; • Shipping.

RAW MATERIALS AND PRODUCTS USED

- Plastic granules, dyes and additives for insulation and sheathing • Copper and other conductive wires • Optical fibres • Metal armouring wires and tapes • Tapes, textile fibres and other accessory materials • Inks and solvents for colouring and printing

SHIFTS, WORKING HOURS

The production lines work on three shifts, including a night shift, depending on production needs: from 6:00 to 14:00, from 14:00 to 22:00, from 22:00 to 6:00.

Offices and warehouses work "day shifts" on a single day shift from 8:00 to 12:00 and from 13:00 to 17:00.

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 6 of 17

MAIN RISKS PRESENT IN THE COMPANY AND MEASURES TO ADOPT

TYPES OF EXISTING RISKS	SOURCE OF RISKS IDENTIFIED	PREVENTION AND PROTECTION MEASURES TO BE IMPLEMENTED
Collisions, Investments 	Possible risk arising from the circulation of means of transport, operating machines and vehicles manoeuvring both within the production departments and outside in the company yards	External personnel must access the intervention sites using the routes established with Management, wearing high-visibility vests of at least "class 2".  The access routes, loading and unloading areas, and temporary storage areas for materials and equipment used by the Contractor must be agreed upon in advance with Management. Mark risk areas and limit access to unauthorized personnel. 
Slips and falls on level ground 	Possible risk arising from the possible spillage of granules or liquids such as water or oil on the floor	External personnel must access the intervention sites using the routes established with the Management, wearing safety footwear of at least "S1P" design.  The access routes, loading and unloading areas, and temporary storage areas for materials and equipment used by the Contractor must be agreed upon in advance with Management. All staff must work to keep corridors, passageways and transit routes clear of objects and materials. Any clutter of materials or accidental spills of liquids on the pavement of passageways and transit routes must be reported to the Management for action. promptly removed.
Falls from a height 	Risk of falling from heights, from stairs and steps, from raised platforms External personnel must access the work areas using the routes established with Management, wearing safety footwear of at least "S1P" design.	External personnel must access the work areas using the routes established with Management, wearing safety footwear of at least "S1P" design.  It is strictly forbidden to tamper with the safety devices and protections installed to protect dangerous elements. It is forbidden to climb on parts of the systems reaching dangerous heights in areas not protected from falls.  Any work at height and access to roofs must be carried out using appropriate safety access systems and adequate protection against falls from a height. 

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 7 of 17

TYPES OF EXISTING RISKS	SOURCE OF RISKS IDENTIFIED	PREVENTION AND PROTECTION MEASURES TO BE IMPLEMENTED
Fallen inside openings, tunnels, pits 	Possible risk of tripping and falling into pits.	External personnel must access the intervention sites using the routes established with Management, wearing footwear with non-slip soles of at least "S1P" design.  It is forbidden to tamper with or remove existing safety devices and guards placed to protect dangerous elements. 
Burns 	Accidental contact with high temperature elements or parts.	External personnel are not authorized to carry out operations using machinery and equipment present in the plant.  External personnel are also required not to tamper with existing safety devices and protections placed to protect dangerous parts or elements  Any interventions to be carried out near machinery and/or near risky operations must be carried out in such a way as to guarantee adequate safety conditions (including by suspending or segregating the operations carried out in the affected area), in collaboration with the company management. Avoid contact with objects or equipment subject to high operating temperatures. Mark the affected areas and limit access to risk areas to unauthorized personnel.

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 8 of 17

TYPES OF EXISTING RISKS	SOURCE OF RISKS IDENTIFIED	PREVENTION AND PROTECTION MEASURES TO BE IMPLEMENTED
Entrapment, amputation, shearing, crushing	Possible risk generated by processing and using machinery and equipment present in the plant without authorization. External personnel are not authorized to carry out operations or use moving parts of machinery in operation at the plant.	 Personnel are also required not to tamper with existing safety devices and protections placed to protect dangerous parts or elements.  Any interventions to be carried out near machinery and/or near risky operations must be carried out in such a way as to guarantee adequate safety conditions (including by suspending or segregating the operations carried out in the affected area), in collaboration with the company management.   Make sure to turn off the power sources on the systems and equipment you are working on, especially for installations in progress and maintenance. Discharge all accumulated power sources and implement a "lock and report" procedure to prevent untimely restarts of the system you are working on.
Projections of materials, fragments or particles	Possible risk generated by processing and using machinery and equipment present in the plant. External personnel are not authorized to carry out operations without authorization.	 External personnel are also required not to tamper with existing safety devices and protections placed to protect dangerous parts or elements.  Any interventions to be carried out near machinery and/or near risky operations must be carried out in such a way as to guarantee adequate safety conditions (including by suspending or segregating the operations carried out in the affected area), in collaboration with the company management.

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 9 of 17

TYPES OF EXISTING RISKS	SOURCE OF RISKS IDENTIFIED	PREVENTION AND PROTECTION MEASURES TO BE IMPLEMENTED
Falling objects or Possible falling objects and risk of suspended loads. Falling materials from shelves or risk of suspended loads. during material handling and loading/unloading phases. 		The presence of external personnel is not permitted in the areas  Movements must take place in conditions of maximum safety without interfering with other work in progress. Movements must be adequately signalled and existing personnel must be alerted by means of appropriate acoustic signals.
Fire/explosion 	Risk of fire due to the presence of combustible and flammable products and the presence of ignition sources in production departments, such as laser welding.	Smoking, using open flames, carrying out work that produces sparks, and charging batteries without authorization are prohibited in the workplace.  The introduction of flammable substances or materials into the plant without authorization is prohibited. The company has fire extinguishing equipment and a team of firefighting workers to ensure adequate extinguishing interventions in the event of a fire.
Noise 	Risk of hearing loss due to possible exposure to noise. During processing, within the production departments it is advisable to use ear protectors such as headphones, sound sources with earplugs or customized inserts. The use of ear protectors is mandatory in the event of noise levels exceeding 80 dB(A) in the Dynamitron department as it is a "hearing risk" area. - -	 If external companies introduce noisy machinery and equipment, they must inform Metallurgica Bresciana S.p.A. management, as part of their safety plans/DUVRI, of the expected noise levels to which both external workers and internal staff may be exposed, so that appropriate measures can be taken.
Mechanical risk from pressure build-up, bursting	compressors, air networks, tanks, cylinders, using machinery and equipment present in the plant, compressed air, pressure vessels, pumps, and hydraulic power units without authorization.	 External personnel are also required not to tamper with existing safety devices and protections placed to protect dangerous parts or elements.  Any interventions to be carried out near machinery and/or near risky operations must be carried out in such a way as to guarantee adequate safety conditions (including by suspending or segregating the operations carried out in the affected area), in collaboration with the company management.

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 10 of 17

TYPES OF EXISTING RISKS	SOURCE OF RISKS IDENTIFIED	PREVENTION AND PROTECTION MEASURES TO BE IMPLEMENTED
Electrical hazard (electrocution, arc flash, and machinery, electrical 	From electrical panels, electrical equipment) to equipment cabins and workshops	External personnel are not authorized to carry out operations using machinery and equipment present in the plant without authorization.  External personnel are required not to tamper with existing safety devices and protections placed to protect dangerous parts or elements of electrical panels, machines, and systems.  Any work on electrical panels and systems must be performed by specialized personnel adequately qualified to perform electrical work. Modifications and repairs to electrical systems must be carried out only when the power is off, taking all precautions required by current regulations regarding electrical work safety. Any work on live systems must be carried out by specialized personnel trained in accordance with the CEI 11-27 technical standard and in accordance with the procedures established for such work, subject to prior authorization from Management.   Agree with company management on the procedure to be implemented for sectioning and securing the part of the electrical system affected by the work. Make sure the electrical power to the systems and equipment you are working on has been disconnected, especially for installations and maintenance. Verify the "zero power" status using the wiring diagram and a tester, which must have been tested for efficiency. Preventively (e.g., on an active electrical outlet). Implement a block-and-signal procedure to isolate energy sources and prevent untimely restarts of the system being serviced.
Chemical risk from gases, fumes, mists, dust	Fumes from the decomposition of rubber and plastic materials are not significant for personnel of external companies, and the risk to health is considered negligible. Any maintenance work on machinery and systems may expose operators to higher levels of exposure. In this case, take appropriate precautions and evaluate the use of appropriate personal protective equipment (protective clothing, gloves, respiratory masks) on a case-by-case basis.	

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 11 of 17

TYPES OF EXISTING RISKS	SOURCE OF RISKS IDENTIFIED	PREVENTION AND PROTECTION MEASURES TO BE IMPLEMENTED
Ionizing radiation Specific risk exists 	External personnel are not authorized to access the Dynamitron facility without authorization from the person responsible at the Dynamitron facility.	 External personnel accessing potentially dangerous areas of the plant must be registered and provided with a dosimeter by the plant manager. External personnel are required not to tamper with existing safety devices and guards protecting dangerous parts or elements of electrical panels, machinery and systems, detectors and safety devices. 

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 12 of 17

OBLIGATIONS OF EXTERNAL PARTIES AND RULES OF CONDUCT

Access to production areas, unless otherwise established, must be accompanied by a Metallurgica Bresciana SpA or OPTOTEC SpA escort.

Staying inside the establishment must be done in strict compliance with these rules. behavioral.

Please note that the correct behavior of your staff, in compliance with established routes, signs, and assigned work tasks in collaboration with our internal managers, will minimize the risks and potential consequences of the risks indicated.

PERSONAL PROTECTIVE EQUIPMENT

External personnel must access the intervention sites using the routes pre-established with Management.

To access the production departments, all external personnel must wear at least: -

Ankle-length trousers, - Safety footwear

in S1P or higher execution (according to EN ISO 20345), Class 2 high-visibility vest

- (according to EN ISO 20471).



Furthermore, if you have to access particularly noisy departments (Dynamitron bunker in operation), you may also need to wear appropriate hearing protection (ear protectors or earplugs).



Any maintenance work on machinery, systems, or specific processes could expose operators to other risks. Appropriate precautions must be taken, evaluating the use of the most appropriate personal protective equipment (clothing, gloves, respiratory masks, fall arrest harnesses, etc.) for the identified risks, as part of their respective safety plans.

FACILITY ACCESS PROCEDURES Your personnel

will perform their work by appointment, arranged well in advance (at least 2 business days) with our purchasing office, who will inform the department managers in which you will be working of your presence.

The work must be carried out on weekdays between 8:00 and 18:00.

Your staff will present themselves at the guest entrance where they will be required to provide their personal details, showing an identity document and the individual identification badge provided by your company.

Your staff must wait at the guest entrance to be received by our security officer or, in any case, by the person responsible for cooperation and coordination between your and our activities in order to avoid possible interference.

Personnel will not be permitted to enter our facility without an identification badge provided by you. The badge must be worn and kept visible at all times while you are at our facility. You will be held solely responsible for any fines imposed due to your staff's failure to display the badge.

Your staff must examine the plant plan indicating the location of the systems and their relative locations, which they must strictly adhere to, avoiding exposure to risks for which they have not been informed and trained.

It is your staff's responsibility to obtain from our safety representative in charge of cooperation and coordination all information on the state of safety at the site and on any particular risk situations and related protection measures in place.

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 13 of 17

Where applicable, upon entering the facility, your staff will have communicated or deposited at the reception desk a list of any equipment and substances brought into the facility. This will also inform us of the risks deriving from your activities and the appropriate protective measures to be adopted.

COOPERATION AND COORDINATION

In addition to your own expertise regarding the risks of your business, it will be your duty and responsibility to inform your staff of the existence and nature of the risks existing in the work environments in which they are called upon to perform their work and to ensure that they are provided with the necessary protection.

If your work requires the temporary removal or deactivation of safety devices on the systems covered by the contract, your personnel will be responsible for implementing equally effective temporary measures and works, taking care to restore any removed or deactivated protections upon completion of the work, suspension of activity, and in any case before abandoning the system.

It is your responsibility to immediately report any deficiencies found to our representatives so that we can eliminate them before continuing your business. It is also your responsibility to immediately report any accident or damage resulting from your work, providing us with all relevant information for health and safety protection.

Should your staff, while carrying out their activities, encounter any abnormal, dangerous, or even unsafe situations, they must immediately notify our safety representative. They must refrain from operating in conditions that pose a risk to their own safety or that of others, and must take steps, within the limits of their competence, to eliminate or reduce the identified deficiencies and dangers.

YOUR OBLIGATIONS

The contractor's personnel must operate equipment in good working order and in compliance with safety standards. They must not use equipment owned by our company without prior written authorization from our safety representative (loan for use).

The contractor's personnel shall not use energy sources other than those required by law and made available within the premises pertaining to the systems undergoing repair and/or maintenance and, where applicable, communicated in the DUVRI.

The personnel sent by you to fulfill the provisions of the contract will operate within our company as your employees and therefore it will be the responsibility of your organization to ensure autonomy, the provision of adequate materials and equipment, the correct information-training and training where necessary, the monitoring of correct operations as well as the management of first aid and evacuation in case of need, as required by current legislation on the matter.

As with the start and end of work, and any suspensions of your activities (whether cessation or resumption) must be promptly communicated to our safety representative, specifying the progress of the work and the prevention measures implemented to ensure the protection of people and plant operations.

At the end of the activity, our safety representative must also be informed (in writing) of the work carried out and any observations deemed useful for the purposes of prevention and protection of people.

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 14 of 17

SPECIFIC DETAILED RULES APPLICABLE TO SOME PROFESSIONAL FIGURES

In addition to the general behavioral rules mentioned above, which apply to any professional figure who may have access to the facility, each figure must follow the specific behavioral instructions for their area of responsibility as described below:

ELECTRICIANS, PLUMBERS, BLACKSMITHS, MAINTENANCE WORKERS

In addition to the general rules, the following specific rules must be respected:

- During the intervention, the machines and systems involved are under the responsibility of the external technicians, who must operate in compliance with safety regulations in order to protect their safety and that of the operators of Metallurgica Bresciana SpA and Optotec SpA, as well as to avoid damaging other existing systems.
- Upon completion of the intervention, operators must verify and ensure that the safety conditions of the machine or system have been restored. Under no circumstances should a machine or system be put into operation if it is not in safe condition or does not comply with legal requirements.

CONSTRUCTION COMPANIES, PAINTERS

In addition to the general rules, the following specific rules must be respected:

- Adopt the provisions of current legislation to prevent the risk of falling from a height, and however, always in the case where work is carried out at a height greater than 2 m.
- If the works fall within the scope of Title IV of Legislative Decree 81/08 regarding temporary or mobile construction sites, the work phases must be carried out in accordance with the provisions of the Operational Safety Plan.
 - Before carrying out

excavations or demolitions, agree on the intervention with the Management, in order to guarantee the impossibility of cutting utilities such as gas or electricity lines.

OIL AND FUEL SUPPLIERS

In addition to the general rules, the following specific rules and those for drivers must be respected:

- Wear gloves, long-sleeved work clothes, safety shoes and use them until the end of the work phase; • Check that the tanker nozzle is correctly inserted into the tank, in order to avoid spills outside the tank; • Check the tank fill level; • In the event of a fuel spill, notify management immediately; • Wash your hands after completing operations; • Monitor operations for the entire time required to load the tank without ever leaving the area; • Once refueling is complete, the employee must go to the weighing/receipt office to collect a copy of the relevant documentation; • In the event of any suspected danger of any nature, the employee must immediately suspend all activity and contact the Metallurgica Bresciana SpA or Optotec SpA staff for instructions.

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 15 of 17

DRIVERS

- Access the facility only at a walking pace and keep the engine running only when absolutely necessary; do not use horns except in an emergency. • Upon arrival, ring the intercom and arrange access times and methods with the relevant offices. Walk to the offices to deliver/receive the administrative documentation for loading/unloading.
- Once you have received instructions from the staff, carry out loading/unloading in accordance with The following:
 - o When approaching the loading and unloading areas, always pay maximum attention to the possible presence of personnel on the ground who could suffer injury from accidental contact or impact, and take care not to obstruct other maneuvering vehicles.
 - o During loading and unloading operations, it is mandatory to follow any instructions from the assigned personnel (e.g., the designated warehouse worker) and follow all phases of the operations.
 - o While waiting, always remain in the driver's cab or, alternatively, in our acceptance/shipping office and, at most, only for the time necessary to check the load, only in the areas related to loading/unloading operations. It is forbidden to move outside these areas.
 - o If the driver must climb onto the vehicle, he or she must implement all protective measures to prevent accidental falls (raising and securing the barrier on the upper walkway, securing the driver with suitable seat belts to any upper attachments, etc.).
 - o Once unloading or loading is complete, drivers of vehicles leaving the plant must go to the acceptance/shipping office to collect a copy of the relevant documentation. • Any other operations not covered by the above must be carried out the preliminary authorization of the plant manager.
- In the event of any suspected dangerous situation of any nature, the transporter must immediately suspend all activities and contact the staff of Metallurgica Bresciana SpA or Optotec SpA for instructions.

ACCESS TO ROOFS, COVERINGS, ELEVATED PLACES • In

- the event of access to elevated places, the personnel in charge will use suitable fixed or retractable ladders, stepladders, and elevating work platforms to safely carry out work at height, using protected walkways near the roofs of the warehouses. • The personnel in charge must be trained and instructed in carrying out work at height, to the use of personal protective equipment and devices to prevent falls.
- The personnel in charge must have adequate equipment to allow them to use both hands to support themselves on the stairs and must refrain from deviating from the prescribed routes shown to them by our safety representative.

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 16 of 17

SPECIFIC RULES APPLICABLE IN CASE OF EMERGENCY-EVACUATION

In case of emergency, public emergency services can be contacted via the telephone numbers listed on the plans displayed in offices and departments. In the event of any emergency or serious and immediate danger, our safety representative or the company's management/reception must be immediately informed to ensure adequate and efficient coordination of the rescue and/or emergency management phases.

A trained and instructed emergency management team is constantly present at the Metallurgica Bresciana SpA and Optotec SpA facilities. The main duties of personnel not directly involved in the emergency, including any visitors or personnel from external companies, are: • In the event of an emergency/evacuation being reported, they follow the instructions of the

Department Manager or Emergency Manager to carry out the operations they are instructed to do. Anyone who is not at their workstation must immediately go to the designated assembly point indicated on the company plans.

- They interrupt any internal or external telephone communication that is not related to the current emergency.
- They carry out the rapid and safe shutdown of systems, equipment, and work in progress.
- They go quickly and in an orderly fashion, without rushing, to the designated assembly point for the attendance check using the nearest emergency exit. • Once the attendance check has been completed at the assembly point, they remain at the disposal of the Manager of the Emergency.
- They do not return to the workplace on their own initiative before the Emergency Manager has announced that the alarm is over.

The evacuation must absolutely not turn into a chaotic and disorderly escape.

Running is prohibited inside the facility.

IDENTIFICATION OF INTERFERENCE RISKS AND MEASURES TO ADOPT

The distribution of this document ensures that external personnel who need to access the company have the necessary information regarding:

- The state of the workplace, the activity carried out, the machinery used; •
- The identification of the dangers present; •
- The measures adopted by company management and those that external personnel must adopt in order to operate safely on site.

In this document, the dangers present in the company have been reported considering the presence of the plants and the workers employed by Metallurgica Bresciana SpA and Optotec SpA without considering the interference caused by any other contractors or third parties who could operate at the site establishment.

Interferences that may arise due to the presence of multiple companies and the prevention and protection measures to be adopted to eliminate them will be analyzed in the DUVRI (Single Risk Assessment Document), compiled jointly in the event of the awarding of works, services, or supplies, if deemed appropriate or mandatory pursuant to art. 26 of Legislative Decree 81/2008.

INFORMATION ON RISKS AND RULES OF CONDUCT FOR EXTERNAL PERSONNEL

Metallurgica Bresciana - Optotec

Dello (BS)

Rev. 08/31/2026

Page 17 of 17

RESPONSIBILITY

Each company department is responsible for:

- distribute this information to its personnel instructed to go for any reason to the Metallurgica Bresciana SpA and Optotec SpA plants located in Dello (BS) in Via Guglielmo Marconi, 31;
- inform your staff about the contents of this instruction; • provide the necessary personal protective equipment for each employee who will be required to go to the Metallurgica Bresciana SpA and Optotec SpA factories; • require that said staff apply the measures contained in this instruction and in the remaining cooperation and coordination documentation;
- provide its staff with a special identification card containing a passport photo, personal details and employer's identification data;
- fill in the DUVRI document Joint Risk Assessment Document in the parts of your competence and return it signed to the client's representative Metallurgica Bresciana SpA or Optotec SpA

Each contractor or self-employed worker visiting the Metallurgica Bresciana SpA and Optotec SpA facilities is responsible for strictly adhering to the contractually established agreements as well as the rules set out in this instruction and in the cooperation and coordination documentation (DUVRI), within their scope of competence.

MINUTES OF ACKNOWLEDGEMENT

In relation to the assignment received from Metallurgica Bresciana SpA or Optotec SpA, the undersigned

..... as Owner/Legal Representative

Representative of the Company/Firm

carrying out the activity of:

Having acknowledged the content of this information, you agree to provide a copy of it to all your personnel assigned to carry out work within the Metallurgica Bresciana SpA and Optotec SpA facilities. This information will be adequately informed and trained for such personnel in compliance with Articles 36 and 37 of Legislative Decree 81/2008.

Place:date:

Stamp and signature of the
Contractor or Self-Employed Worker

.....