**INPUTS OUTPUTS** CLR CLK  $Q_B$ В  $Q_{\Delta}$  $Q_H$ ¥ Y

**FUNCTION TABLE**(1)(2)

_	/	^	^	_	_	_
Н	L	X	X	$Q_{A0}$	$Q_{B0}$	$Q_{H0}$
н	<b>↑</b>	н	н	н	0	00-

ЧAп  $Q_{Gn}$  $Q_{An}$ 

 $Q_{\Delta n}$  $Q_{Gn}$ (1)Q<sub>A0</sub>, Q<sub>B0</sub>, Q<sub>H0</sub> = the level of Q<sub>A</sub>, Q<sub>B</sub>, or Q<sub>H</sub>, respectively, before the

indicated steady-state input conditions were established. (2) $Q_{An}$ ,  $Q_{Gn}$  = the level of  $Q_A$  or  $Q_G$  before the most recent  $\uparrow$  transition

of CLK: indicates a 1-bit shift.