



Prepared by : MUHTAROM ASIDIQ (PRODUCTION TRAINING)



Tujuan Penerapan Kesehatan dan Keselamatan Kerja:

Kecelakaan kerja dapat terjadi karena kondisi yang tidak membawa keselamatan kerja, atau perbuatan yang tidak selamat.

Kecelakaan kerja dapat didefinisikan sebagai setiap perbuatan atau kondisi tidak selamat yang dapat mengakibatkan kecelakaan.

Cara menanggulangi kecelakaan kerja

adalah dengan meniadakan unsur penyebab kecelakaan dan atau mengadakan pengawasan yang ketat.





Tujuan dari keselamatan dan kesehatan kerja adalah sebagai berikut:

- a. Agar setiap pegawai mendapat jaminan keselamatan dan kesehatan kerja baik secara fisik, sosial, dan psikologis.
- b. Agar setiap perlengkapan dan peralatan kerja digunakan sebaik-baiknya selektif mungkin.
- c. Agar semua hasil produksi dipelihara keamanannya.
- d. Agar adanya jaminan atas pemeliharaan dan peningkatan kesehatan gizi pegawai.
- e. Agar meningkatkan kegairahan, keserasian kerja, dan partisipasi kerja.
- f. Agar terhindar dari gangguan kesehatan yang disebabkan oleh lingkungan atau kondisi kerja.
- g. Agar setiap pegawai merasa aman dan terlindungi dalam bekerja



Indikator penyebab Kecelakaan Kerja adalah:

- a) Keadaan tempat lingkungan kerja, yang meliputi:
- 1. Penyusunan dan penyimpanan barang-barang yang berbahaya yang kurang diperhitungkan keamanannya.
 - 2. Ruang kerja yang terlalu padat dan sesak
 - 3. Pembuangan kotoran dan limbah yang tidak pada tempatnya.
- b) Pemakaian peralatan kerja, yang meliputi:
 - 1. Pengaman peralatan kerja yang sudah usang atau rusak.
 - 2. Penggunaan mesin, alat elektronik tanpa pengaman yang baik pengaturan penerangan.



SIMBOL	ARTI SIMBOL	SIMBOL	ARTI SIMBOL
	RISK OF GETTING TRAPPED do not insert hands BAHAYA TERJEPIT jangan memasukkan tangan		Do not get caught in the machine serious injury can result Jangan masuk ke dalam mesin dapat menyebabkan cidera serius
4	HIGH VOLTAGE do not touch TEGANGAN TINGGI jangan disentuh atau dipegang		BEWARE OF CUTTING EDGES do not insert hands HATI-HATI UJUNG PEMOTONG jangan memasukkan tangan
	CAUTION UV do not see the UV Lamp while in operation HATI - HATI SINAR UV jangan melihat sinar lampu UV saat mesin beroperasi		BEWARE OF GETTING CAUGHT UP in moving parts HATI-HATI TERTARIK komponen yang bergerak



SIMBOL	ARTI SIMBOL	SIMBOL	ARTI SIMBOL
	HIGH TEMPERATURE do not touch TEMPERATUR TINGGI jangan tersentuh tangan		PRIMARY AIR PRESS. MAX 1.0MPa SECONDARY AIR PRESS MIN 0.5MPa Tekanan Udara Primer max 1.0MPa. Tekanan Udara Secondary min 0.5MPa
	HAZARDOUS VOLTAGE Turn off power before opening cover BAHAYA TEGANGAN TINGGI matikan power sebelum membuka cover mesin		CAUTION ! SPINNER Hati-hati Part Berputar
	Moving part can crush hand. Keep hands away from moving parts. Turn off power before servicing Part bergerak dapat merusak tangan. Jauhkan tangan. Matikan power saat melakukan perbaikan.		Magazine Moving Up & Down, Right & Left. You will have serious injury if you touch moving magazine Hati-hati magazine bergerak. Anda akan terluka jika menyentuh magazine yang bergerak.



SIMBOL	ARTI SIMBOL	SIMBOL	ARTI SIMBOL
4	HIGH VOLTAGE You will have serious electric shock if touch electric power supply inside TEGANGAN TINGGI Anda akan tersengat listrik tegangan tinggi jika menyentuh sumber power		CAUTION! Outside walls and parts are hot during and after operation HATI-HATI Dinding luar dan komponen panas saat dan setelah operasi
	HOT SURFACE You will have serious burn if you touch the hot surface PENAMPANG PANAS Anda akan luka terbakar jika menyentuh penampang panas		DANGER! Hazardous moving parts. Don't open the cover during operation. BERBAHAYA Bahaya part bergerak. Jangan membuka cover saat beroperasi
<u>SSSS</u>	CAUTION! Hot Surface, Burm Hazard HATI - HATI Penampan panas, bahaya terbakar		Caution on entanglement of hands or fingers. Close panel during operation. Hati-hati tangan, jari tertarik mesin. Tutup panel saat mesin beroperasi



SIMBOL	ARTI SIMBOL	SIMBOL	ARTI SIMBOL
A	HIGH VOLTAGE Can result electric shock, serious burn or death Only authorize maintenance personel may handle this part. Turn power off before maintenance. BAHAYA TEGANGAN TINGGI Dapat menyebatkan kesetrum, terbakar, atau kematian. Only PIC teknisi dapat melakukannya. Matikan mesin sebelum melakukan perbaikan.		RADIO FREQUENCY RADIATION Can cause inductive heating or failure of medical devices. Turn power off before removing the cover. RADIASI FREQUENSI RADIO Dapat menyebabkan panas induktif atau kerusakan peralatan kesehatan. Matikan Power sebelum membuka covernya.
	During packaging, do not place hand or fingers in the sealing area. Burns or pinching may occur. Saat proses packing, posisi tangan jangan di area sealing. Menyebabkan luka atau terjepit.		CAUTION NOZZLE! Pay attention to the nozzle moving forward or backward during vacuum. Pinching may accur. HATI-HATI NOZZLE! Perhatikan gerakan nozzle maju atau mundur saat proses vacuum. Cidera luka dapat terjadi



SIMBOL	ARTI SIMBOL	SIMBOL	AR
	CHRUSH HAZARD May result in severe injury. Turn power off before removing the cover. BAHAYA TERJEPIT Dapat menyebabkan cidera. Matikan power sebelum membuka covernya.		Inside ente pe HATI-HATI! ke dalam m sudah
00000	NIP POINT! Moving part NIP POINT! Part bergerak		HAZARI Can cause se Disconnect of prio BAHAYA TE Dapat men kematian. Ma
Green Gas	WARNING OF GREEN GAS CHOKING HAZARD Bahaya Green gas	Argon	WARNING C Baha



SIMBOL	ARTI SIMBOL	SIMBOL	ARTI SIMBOL
CO ₂	WARNING OF CO2 CHOKING HAZARD Bahaya Gas CO2		CAUTION! This unit generated Laser beam, do not exposed while in operation HATI - HATI! jangan melihat sinar laser saat mesin beroperasi
N ₂	WARNING OF N2 CHOKING HAZARD Bahaya Gas N2		CAUTION! This unit is sensitive to static electricity. Handle with care. HATI-HATI! Unit ini sensitive pada listrik statis. Perlakukan hati-hati.
	FIRE HAZARD ! HIGHLY FLAMMABLE Bahaya Terbakar ! Sangat mudah		CAUTION! Hot Surface, Caution on burn. HATI-HATI Permukaan panas, bahaya luka terbakar



SIMBOL	ARTI SIMBOL	SIMBOL
	Only a maintenance engineer is allowed to open the cover. High voltage may cause an electric shock.	
	Hanya Engineering yang membuka cover ini. Tegangan tinggi dapat menyebabkan bahaya kesetrum.	
	Obstruction Keep clear of moving parts such as gears to prevent fingers or sleeves from getting caught.	
	Besihkan penghalang terhadap part yang bergerak seperti gear untuk menghindari lengan terjepit mesin	
	CAUTION! Outside walls and parts are hot during and after operation	1 - D
	HATI-HATI Dinding luar dan komponen panas saat dan setelah operasi	

MOVING SECTION Can cause injury to extremities, Keep safety cover closed while equipment is running. Turn power

ARTI SIMBOL

LOKASI PART BERGERAK
Dapat menyebabkan luka berat, Jaga
safety cover tetap tertutup saat
mesin berjalan. Matikan mesin
sebelum melakukan perbaikan.

off before performing maintenance.

ROTATING SECTION Do not touch this part while equpment is running. Can cause injury to extremities. Turn power off before performing maintenance.

LOKASI PART BERPUTAR
Jangan menyentuh bagian ini saat
mesin beroperasi. Dapat
menyebabkan luka berat. Matikan
mesin sebelum melakukan
perbaikan.



SIMBOL	ARTI SIMBOL	SIMBOL	ARTI SIMBOL	
	MOVING SECTION Do not touch this part while equpment is running. Can cause injury to extremities. Turn power off before performing maintenance. LOKASI PART BERGERAK Jangan menyentuh bagian ini saat		DON'T OPEN THE COVER refer servicing to properly trained personel DILARANG MEMBUKA COVER untuk servis harus oleh orang yang sudah di training	
	mesin beroperasi. Dapat menyebabkan luka berat. Matikan mesin sebelum melakukan perbaikan.		DON'T OPEN THE COVER refer servicing to properly trained personel DILARANG MEMBUKA COVER untuk servis harus oleh orang yang sudah di training	
**	Low Temperature Temperatur Rendah		Do not open the safety cover during operation. The equipment stops immediately. Jangan membuka cover pengaman saat mesin beroperasi. Mesin akan berhenti.	



SIMBOL	ARTI SIMBOL	SIMBOL	ARTI SIMBOL
	PROTECTIVE CLOTHING MUST BE WORN WHEN WORKING AT THIS AREA BAJU PELINDUNG HARUS DIPAKAI SAAT BEKERJA DI AREA INI		EXPLOSION! Don not operate chamber with flamable/explosive substances inside BAHAYA LEDAKAN Jangan mengoperasikan chamber dgn bahan yang dapat terbakar/meledak
	FIX THE LEVELER AFTER INSTALLATION OF THIS INSTRUMENT PERBAIKI LEVELER SETELAH INSTALASI PERALATAN		Never touch moving part when power is on Your hands may be caught in machine Jangan menyentuh part bergerak saat power menyala, tangan anda akan terjepit mesin
	SAFETY SHOES MUST BE WORN WHEN WORKING AT THIS AREA SAFETY SHOES HARUS DIPAKAI SAAT BEKERJA DI AREA INI		Do not disable safety Sensor You will have serious enjury by active part if you disable safety sensor Jangan menonaktifkan sensor pengaman. Anda akan terluka oleh part bergerak jika sensor tidak aktif.



SIMBOL	ARTI SIMBOL	SIMBOL	ARTI SIMBOL
	SECURE COMPRESSED GAZ BOTTLE WITH CHAIN AMANKAN TABUNG GAS DENGAN PENGAMAN RANTAI		EAR PROTECTION MUST BE WORN WHEN WORKING AT THIS AREA APD TELINGA HARUS DIPAKAI SAAT BEKERJA DI AREA INI
	APrON MUST BE WORN WHEN WORKING AT THIS AREA APRON HARUS DIPAKAI SAAT BEKERJA DI AREA INI		RESPIRATORY PROTECTION MUST BE WORN WHEN WORKING AT THIS AREA MASKER KHUSUS HARUS DIPAKAI SAAT BEKERJA DI AREA INI
	SAFETY GLASS MUST BE WORN WHEN WORKING AT THIS AREA SAFETY GLASS HARUS DIPAKAI SAAT BEKERJA DI AREA INI		DON'T OPEN THE COVER DILARANG MEMBUKA COVER MESIN



TEBINANASII.