


COMPLIANCE SCANNER CALIBRATION CARD

Legal Metrology (Packaged Commodities) Rules, 2011




ArUco DICT_4X4_50, id 0

Nominal side: 40 mm

MEASURE IT AFTER PRINTING.

Printers scale. Pass the measured
value as --marker-mm, not 40.

Verification scale - check against a real ruler:



HOW TO USE

1. Print this page at 100% scale (no 'fit to page', no scaling).
2. Measure the printed black square edge-to-edge with a ruler or calipers. Confirm the 100 mm scale above reads 100 mm.
3. Lay the card FLAT AGAINST the label panel, in the SAME PLANE.
The card and the printed declarations must be coplanar - this is what makes a photograph carry physical scale at all.
4. Photograph both together, as square-on as practical.
5. Scan, passing the measured side length:

```
python backend/lmpc/cli.py scan photo.jpg --marker-mm 40.0
```

WHY A MARKER IS REQUIRED

A photograph has no inherent physical scale: the same pixel height could be small print close up or large print far away. The marker is the only thing in frame with a known real-world size, so it is what converts pixels to millimetres. It is re-detected in EVERY frame, so moving or bumping the camera cannot silently invalidate the scale.

SCOPE

Flat / near-flat printed packaging only. Curved surfaces (bottles, jars, cans) break the coplanarity assumption. Embossed and debossed text is out of scope - it needs raking light to be visible at all.