

Sheet 0 - E-Authorization Data

A350-XWB		STATUS: OFFICIAL(Full TRS)
XW CEF	L26118	ISSUE: 2
		OFFICIAL DATE: 08-Aug-2018

TITLE:
E.a.E. - Cable Loom Inst. drawings - Modify harnesses installation for OHSC in Door Zone D3
LH FWD (sol. G)

COORDINATOR: LAFORSE Christine

REASON: Request for Product Customization - Customization Administrative Issue - SY-Other Systematic Action;

	DESIGN OFFICE (As required)	AIR WORTHINESS (As required)	CM CHECKER (As required)	HEAD OF ENGINEERING OR REPRESENTATIVE	HEAD OF CONFIGURATION MANAGEMENT OR REPRESENTATIVE
NAME	ESTANOS JEAN- PHILIPPE - TO26811	ZIPELIUS JEROME - ZIPELIUS_JE	BERTRAND BRIGITTE - TO33803	LAVIOLETTE DAMIEN - TO76559 (Approver)	AZAM SEBASTIEN - TO96923 (Authorizer)
DATE	08-Aug-2018	07-Aug-2018	07-Aug-2018	08-Aug-2018 (Approver)	08-Aug-2018 (Authorizer)



Technical Repercussion Sheet Sheet 0 - History

A350-XWB		STATUS: OFFICIAL (Full TRS)
XW CEF	L26118	ISSUE: 2
		LAST UPDATE: 07-Aug-2018

TITLE: E.a.E Cable Loom Inst. drawings - Modify harnesses installation for OHSC in Door Zone D3 LH FWD (sol. G)	ATA : 9280
LITEWD (Sol. G)	COORDINATOR: LAFORSE Christine

REASON: Request for Product Customization - Customization Administrative Issue - SY-Other Systematic Action;

ISSUE	DATED	AUTHOR	COMMENT / REASON	SIGNATURE LOOP
2	07-Aug-2018	LAFORSE Christine	XW CEF FULL TRS	Normal
1	03-Sep-2015	CHAVAROCHE BENEDICTE	TRS ready for mod opening	Normal



Sheet 1

,		
A350-XWB	L26118	STATUS: OFFICIAL (Full TRS)
XW CEF		ISSUE: 2
		LAST UPDATE: 07-Aug-2018

TITLE:

E.a.E. - Cable Loom Inst. drawings - Modify harnesses installation for OHSC in Door Zone D3

LH FWD (sol. G)

ATA: 9280

COORDINATOR: LAFORSE Christine

REASON: Request for Product Customization - Customization Administrative Issue - SY-Other Systematic Action;

ORIGIN DOCUMENTS: RFC-VIR25V029I-Door zones layout definition

EXPECTED APPLICABILITY:

Customer version

NECESSARY TO OBTAIN/MAINTAIN TYPE CERTIFICATE: No

CLASSIFICATION: W - NO FURTHER SHOWING OF COMPLIANCE

A/C CATEGORY: CIVIL MODEL(S): 350-1041;

IMPLEMENTATION CONDITION: SERIE SOLUTION ONLY

SB PROPOSED BY ENGINEERING: No INTERCHANGEABILITY AFFECTED: No ENGINEERING DEADLINE: POWER ON

TO BE EMBODIED BEFORE: None

RESTRICTIONS CANCELLED BY THIS MODIFICATION: None

GENERAL DESCRIPTION:

The modification consists in modifying harnesses installation for OHSC in Door Zone D3 LH FWD (sol. G)

Abbreviations

OHSC: overhead stowage compartment

D3: door 3 LH: left hand FWD: forward Sol.: solution

LINKED MODIFICATIONS: Associated with 101202;

COMMENT: 101202 E.A.E.COM.INST.-CABLE LOOM INST.DWGS INSTALL HARNESSES FOR OHSC STANDARD ARCHITECTURE IN

CENTER FUSELAGE



Alliabos		
A350-XWB		STATUS: OFFICIAL (Full TRS)
XW CEF	L26118	ISSUE: 2
		LAST UPDATE: 07-Aug-2018



A350-XWB	L26118	STATUS: OFFICIAL (Full TRS)
XW CEF		ISSUE: 2
		LAST UPDATE: 07-Aug-2018

REGULATIONS INVOLVED AND JUSTIFICATION:

Certification Basis:

TCDS EASA.A.151 / TCDS FAA T00063IB

Certif.Basis	FIC	ATA	A/W & Environmental Requirement	MoC	
--------------	-----	-----	---------------------------------	-----	--

Compliance statement:

No additional work to show compliance with the applicable certification basis including FAR26 requirements. Availability (as required by Part 21) of any impacted other ICA is managed in accordance with DOM procedures.

Comment:

IPACTS ON EQUIPMENT
ruinment sorted hy: Family

DOCUMENT TYPE	STATEMENT	DESCRIPTION
SRM ADL/REPAIR	NO	
WBM Chapter 1.10 limitations	NO	
MMEL	NO	
FM - Flight Manual	NO	
MRB - Maintenance Review Board	NO	
ALS Part 1	NO	
ALS Part 2	NO	
ALS Part 3	NO	
ALS Part 4	NO	
ALS Part 5	NO	
Security HandBook	NO	
EWIS ICA	NO	
Other ICA	YES	
Flight Crew Data		
Cabin Crew Data		




Sheet 3 (Sketches)

A350-XWB		STATUS: OFFICIAL (Full TRS)
XW CEF	L26118	ISSUE: 2
		LAST UPDATE: 07-Aug-2018

SECTION 15/21 SKETCHES

ATA92-00 Electrical and Electronic Common Installation - General


SYNOPTIC:





Sheet 3 (Sketches)


A350	0-XWB		STATUS: OFFICIAL (Full TRS)
XW (CEF	L26118	ISSUE: 2
			LAST UPDATE: 07-Aug-2018





Technical Repercussion Sheet Sheet 3 (Sketches)

A350-XWB		STATUS: OFFICIAL (Full TRS)
XW CEF	L26118	ISSUE: 2
		LAST UPDATE: 07-Aug-2018





A350-XWB		STATUS: OFFICIAL (Full TRS)
XW CEF	L26118	ISSUE: 2
		LAST UPDATE: 07-Aug-2018

ADDITIONAL ATA: 9200; 9240; 9290;

IMPACT ON VERIFICATION / VALIDATION MEANS:				
MOCK UP	FATIGUE TESTS	GROUND TESTS	LABORATORY TESTS	
NO	NO	NO	NO	
PARTIAL BENCH	IRON BIRD	FLIGHT TESTS		
NO	NO	NO		
COMMENT:				

IMPACTS ON WEIGHT:				
SERIE	DELTA ON MWE WEIGHT (kg)	CG OF THE DELTA MWE (m)	ORIGIN SUB-TRS	
350-1000	0.217	0.0		
TOTAL:				
350-1000	0.217	0.0		
COMMENT: CG not calculated				

ELECTRICAL LOADS IMPACTED: NO

COMMENT:

IMPACTED DOCUMENTATION:

Impacted airlines documentations identified by customer service are available in CM reporting

COMMENT:

IMPACTED STANDARD SPE	MPACTED STANDARD SPECIFICATION			
REFERENCE	ISSUE	REVISION	TEMP.REVISION	ISSUE DATE
PROPOSED UPDATE:				
MSCN:NO		CLASSIFICATION NEGOTIA	ABLE:NA	
MSCN JUSTIFICATION:		•		



Sheet 4

Filitous		
A350-XWB		STATUS: OFFICIAL (Full TRS)
XW CEF	L26118	ISSUE: 2
		LAST UPDATE: 07-Aug-2018

DETAILED DESCRIPTION:

SECTION 15/21 REPERCUSSIONS

Electrical Systems impacts

Electrical systems installation repercussions

ATA 92-00 - Electrical and Electronic Common Installation - General

E.a.E. - Cable Loom Inst. drawings - Modify harnesses installation for OHSC in Door Zone D3 LH FWD (sol. G).

Standard Statements for Stress Impact

This change has no stress impact.

ATA92-40 Electrical and Electronic Common Installation – Installation Drawings of Removable Supports

S15/21 - UD-LAT FR61 to FR64

Quantity of new reference of V924 created: 0 unloaded, 0 loaded

Loaded / Unloaded	New (n-1) added qty	Details
Unloaded	0	Remove 1 jumper small
Unloaded	0	Add 2 IF plates
Unloaded	0	Add 1 ramp BB/OD

Weight impact ATA92-40: + 0.283 Kg

ATA92-80 Electrical and Electronic Common Installation – Cable Loom Installation Drawings

S15/21 - UD-LAT FR61 to FR64

Modify installation as shown in Sketch CEF_ESI_HAR_EQT_1:

CEF UD MLH MD/M CTAFT: To remove 3 clips nut between FR62 and FR63.	NZ
To relocate 4 clamps between FR62 and FR63.	NZ
CEF UD MLH MD/M AFT: To remove 9 clamps + 4 spacers + 1 clip nut between FR63 and FR64.	NZ
CEF UD Z5-6 MLH HAT: To add 8 clamps + 8 spacers between FR62 and FR64.	NZ
CEF UD ML ASS DMD RTG	NZ
CEF UD IM CTAFT	NZ

Weight impact ATA92-80: - 0.066 Kg



Sheet 4

A350-XWB		STATUS: OFFICIAL (Full TRS)
XW CEF	L26118	ISSUE: 2
		LAST UPDATE: 07-Aug-2018

ATA92-90 Electrical and Electronic Common Installation – Cable Loom Drawings

S15/21 - UD-LAT FR61 to FR63

Modify installation as shown in Sketch CEF_ESI_HAR_EQT_1:

Harness 1809VB 11M Harness 1719VB 1MD Harness 2763VB 11M Harness 2563VB 1MD

Weight impact ATA92-90: + 0.000 Kg

Total CEF ESI HAR and EQT weight impact (924 + 928 + 929):	+ 0.217 Kg
--	------------

The design requirements and principles as referenced in the TDD2QA001V. SIDP20A001V, TDD92A001V, SIDP92A001V, are maintained.



FIII		
A350-XWB	L26118	STATUS: OFFICIAL (Full TRS)
XW CEF		ISSUE: 2
		LAST UPDATE: 07-Aug-2018

IMPACTS ON CIRCUIT - ATA's (Leader impacts; refer to sub-TRS for involved impacts):				
CIRCUIT	ATA	BREAKDOWN CODE		
VB	9200	F		
LEAD-TIME (WEEKS):				

IMPACTS ON CASCADE COMPONENTS (Leader impacts; refer to sub-TRS for involved impacts):						
TYPE	CODE	TITLE	ATA	BREAKDOWN CODE	LEAD-TIME (WEEKS)	

IMPACTS ON HARNESSES AND PANELS (Leader impacts; refer to sub-TRS for involved impacts):				
TYPE	CODE	TITLE	ASSOCIATED TO CA	

IMPACTS ON ADAP-CI / RF's (Leader impacts; refer to sub-TRS for involved impacts):					
ADAP-CI CODE	LEGACY CODE	TITLE	CA	LEAD-TIME (WEEKS)	
W92C11719000	NA	HARNESS 1719VB 1MD	WD352		
W92C11809000	NA	HARNESS 1809VB 11M	WD354		
W92C22563000	NA	HARNESS 2563VB	WD419		
W92C22763000	NA	HARNESS 2763VB	WD438		
W92C34309000	NA	CEF UD ML ASS DMD RTG	WD019		
W92C34423000	NA	CEF UD MLH MD/M CTAFT	WD019		
W92C34433000	NA	CEF UD Z5-6 MLH HAT	WD019		
W92C34445000	NA	CEF UD IM CTAFT	WD000		
W92C34451000	NA	CEF UD MLH MD/M AFT	WD019		

IMPACTS ON ESD-CI's (Leader impacts; refer to sub-TRS for involved impacts):				
TYPE	CODE	DESIGNATION	ASSOCIATED TO CA/CC	

OTHER IMPACTS:				
PROPULSION SYSTEM	SERIE GTR IMPACTED	SPECIAL SUPPLY	PARTS	RIGGING / TOOLING
			INTERCHANGEABILITY	
NO	NO	NO	NO	NO
COMMENT:				



FUILDOS		
A350-XWB		STATUS: OFFICIAL (Full TRS)
XW CEF	L26118	ISSUE: 2
		LAST UPDATE: 07-Aug-2018

TRS COORDINATOR: XW CEF				
DESIGN INVOLVEMENT:				
NATCO / OBS	NATCO	STANDARD		
XW CEF	A-F			
DESIGN RESPONSIBLE:BOUBEKEUR Jean-luc				

ACTIVITIES:				
COST CHAPTER	ACTIVITY TYPE	ACTIVITY	RESP.	
01. Design			XW CEF	
08. Production			XW CEF	
COMMENT:				