

AI Based road condition assessment detailed report by ROAD ATHENA RO : Chandigarh PIU : Ambala



Date of survey: 2024-09-26

			Segment	name: Ambala to F	Pehowa of Nh- 65 i	n Haryana (Packa	ge-1) LHS	
Start Chainage	0							
End Chainage	50860							
Anomaly Number	Timestamp on processed video	Anomaly type	Side	Category	Latitude	Longitude	Distance from start point in meters	Image Link
1	2024-09-25 11:11:21	DAMAGED_SIGN	Median	Cautionary Signs	30.290780833	76.7175355	17241.89531613	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_283 1.jpg
2	2024-09-25 11:12:03	DAMAGED_SIGN	Avenue	Informatory Signs	30.287786167	76.7167415	17584.80977043	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_408 8.jpg

3	2024-09-25 11:15:44	DAMAGED_SIGN	Avenue	Cautionary Signs	30.275158333	76.715704333	19120.33368075	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_531 9.jpg
4	2024-09-25 11:16:31	DAMAGED_SIGN	Avenue	Cautionary Signs	30.272649833	76.714353	19433.01041359	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0015_134 3.jpg
5	2024-09-25 11:31:36	DAMAGED_SIGN	Median	Cautionary Signs	30.2076335	76.702417667	26936.79313224	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_27.png
6	2024-09-25 11:39:32	DAMAGED_SIGN	Median	Cautionary Signs	30.1771945	76.697745833	30535.57053159	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0022_495 6.jpg
7	2024-09-25 12:05:02	DAMAGED_SIGN	Avenue	Cautionary Signs	30.075663167	76.669675	42769.3546988	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_41.png

8	2024-09-25 12:05:56	DAMAGED_SIGN	Avenue	Cautionary Signs	30.071615167	76.669207167	43228.45632882	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_42.png
9	2024-09-25 12:06:02	DAMAGED_SIGN	Avenue	Cautionary Signs	30.071192333	76.668881833	43284.62689224	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_56.png



AI Based road condition assessment detailed report by ROAD ATHENA RO : Chandigarh PIU : Ambala



Date of survey: 2024-09-26

			Segment	name: Ambala to F	Pehowa of Nh- 65 i	n Haryana (Packa	ge-1) LHS	
Start Chainage	0							
End Chainage	50860							
Assets Number	Timestamp on processed video	Asset type	Side	Category	Latitude	Longitude	Distance from start point in meters	Image Link
2	2024-09-25 10:33:53	HAZARD	Avenue	Cautionary Signs	30.413326833	76.783286833	16.19778723287	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0001_100. jpg
3	2024-09-25 10:34:06	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.413322667	76.782846	60.60962005756	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0001_501. jpg

		,						
4	2024-09-25 10:34:23	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.4132765	76.781934	150.8181428783	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0001_991. jpg
5	2024-09-25 10:34:52	HAZARD	Avenue	Cautionary Signs	30.413167833	76.779956667	340.5863067038	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0001_188 9.jpg
6	2024-09-25 10:35:38	CHEVRON	Median	Cautionary Signs	30.413154	76.776774333	647.5213418783	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0001_325 1.jpg
7	2024-09-25 10:35:47	CHEVRON	Median	Cautionary Signs	30.413167167	76.776127333	709.9923663763	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0001_352 2.jpg

8	2024-09-25 10:35:55	CHEVRON	Median	Cautionary Signs	30.413150833	76.775529833	767.3552879201	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0001_377 8.jpg
9	2024-09-25 10:36:01	HAZARD	Avenue	Cautionary Signs	30.413114	76.775093167	809.7059477227	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0001_394 1.jpg
10	2024-09-25 10:36:33	CHEVRON	Median	Cautionary Signs	30.412773667	76.772475167	1065.039769138	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0001_491 5.jpg
11	2024-09-25 10:36:39	CHEVRON	Median	Cautionary Signs	30.412630333	76.771987667	1115.002786771	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0001_507 5.jpg

12	2024-09-25 10:36:43	CHEVRON	Median	Cautionary Signs	30.412503833	76.7716595	1149.801157849	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0001_521 4.jpg
13	2024-09-25 10:36:48	CHEVRON	Median	Cautionary Signs	30.4123205	76.771254833	1193.543083181	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0001_534 9.jpg
14	2024-09-25 10:37:54	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.409931	76.766148	1750.728453378	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0002_198 2.jpg
15	2024-09-25 10:38:02	HAZARD	Avenue	Cautionary Signs	30.4096725	76.765537	1816.107652897	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0002_224 9.jpg

16	2024-09-25 10:38:07	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.409529667	76.765139833	1857.567900371	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0002_237 8.jpg
17	2024-09-25 10:38:13	CHEVRON	Avenue	Cautionary Signs	30.409390333	76.764660667	1905.597457096	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0002_257 5.jpg
18	2024-09-25 10:38:23	CHEVRON	Avenue	Cautionary Signs	30.409234	76.763854333	1985.970042721	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0002_285 3.jpg
19	2024-09-25 10:38:26	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.409202833	76.763581667	2002.694018844	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_1.png

20	2024-09-25 10:38:32	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.409156333	76.763008667	2068.430448464	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0002_314 5.jpg
21	2024-09-25 10:39:12	PROHIBITORY_M ANDATORY_SIG NS	Avenue	Mandatory Signs	30.408906167	76.759308167	2414.303004034	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_2.png
22	2024-09-25 10:40:21	INFORMATORY_ SIGNS	Median	Informatory Signs	30.408519667	76.753368333	2987.048991753	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_3.png
23	2024-09-25 10:40:28	INFORMATORY_ SIGNS	Median	Informatory Signs	30.408520333	76.752761333	3044.606237444	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_4.png
24	2024-09-25 10:40:35	PROHIBITORY_M ANDATORY_SIG NS	Median	Mandatory Signs	30.408517	76.752241833	3103.757032939	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0003_141 4.jpg

25	2024-09-25 10:40:42	CHEVRON	Median	Cautionary Signs	30.408516	76.751726	3143.707388458	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_5.png
26	2024-09-25 10:40:44	PROHIBITORY_M ANDATORY_SIG NS	Median	Mandatory Signs	30.408515	76.751574333	3168.233243832	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0003_168 9.jpg
27	2024-09-25 10:40:54	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.408511833	76.750905667	3229.219177309	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0003_200 9.jpg
28	2024-09-25 10:40:59	CHEVRON	Median	Cautionary Signs	30.408509333	76.750682167	3252.106265673	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0003_214 2.jpg

29	2024-09-25 10:41:07	CHEVRON	Median	Cautionary Signs	30.408504167	76.750197333	3299.579775664	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0003_238 3.jpg
30	2024-09-25 10:41:18	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.408478	76.749432	3373.59032481	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0003_271 6.jpg
31	2024-09-25 10:41:20	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.4084685	76.749293333	3386.976644186	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0003_277 1.jpg
32	2024-09-25 10:41:22	CHEVRON	Median	Cautionary Signs	30.408457833	76.749154833	3400.272123707	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0003_282 2.jpg

33	2024-09-25 10:41:34	HAZARD	Median	Cautionary Signs	30.40828	76.748341667	3481.148449946	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0003_318 8.jpg
34	2024-09-25 10:41:42	CHEVRON	Median	Cautionary Signs	30.408060833	76.747812167	3538.277572543	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0003_343 8.jpg
35	2024-09-25 10:41:49	CHEVRON	Median	Cautionary Signs	30.407789167	76.747348167		https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0003_363 5.jpg
36	2024-09-25 10:41:55	CHEVRON	Median	Cautionary Signs	30.4075235	76.746966	3639.59703546	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0003_382 5.jpg

37	2024-09-25 10:42:49	CHEVRON	Median	Cautionary Signs	30.404935667	76.743493833	4079.947151038	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0004_58.j pg
38	2024-09-25 10:42:57	CHEVRON	Median	Cautionary Signs	30.4045625	76.742989667	4143.423439833	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0004_288. jpg
39	2024-09-25 10:43:04	CHEVRON	Median	Cautionary Signs	30.404240667	76.7425625	4197.810912955	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0004_488. jpg
40	2024-09-25 10:43:10	CHEVRON	Median	Cautionary Signs	30.403947	76.7421985	4245.779915833	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0004_663. jpg

41	2024-09-25 10:43:28	HAZARD	Avenue	Cautionary Signs	30.4029835	76.741212833	4388.512365618	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0004_120 4.jpg
42	2024-09-25 10:43:37	CHEVRON	Median	Cautionary Signs	30.402454167	76.740794	4460.177417136	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0004_148 8.jpg
43	2024-09-25 10:43:51	CHEVRON	Median	Cautionary Signs	30.401464833	76.740171833	4585.388394267	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0004_190 9.jpg
44	2024-09-25 10:46:12	CHEVRON	Median	Cautionary Signs	30.391665833	76.735830833	5749.084431202	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0005_739. jpg

-								
45	2024-09-25 10:46:27	PROHIBITORY_M ANDATORY_SIG NS	Median	Mandatory Signs	30.3907285	76.735483667	5857.316458294	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0005_119 6.jpg
46	2024-09-25 10:46:29	PROHIBITORY_M ANDATORY_SIG NS	Median	Mandatory Signs	30.390613667	76.735441833	5870.673218279	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0005_124 7.jpg
47	2024-09-25 10:47:02	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.3887575	76.735110833	6080.396714076	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0005_223 3.jpg
48	2024-09-25 10:47:24	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.3874005	76.735049667	6230.079502213	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0005_288 6.jpg

49	2024-09-25 10:47:35	HAZARD	Median	Cautionary Signs	30.386726	76.734972833	6306.138350533	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0005_321 7.jpg
50	2024-09-25 10:48:47	HAZARD	Avenue	Cautionary Signs	30.381650667	76.734880667	6868.567653129	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0005_537 2.jpg
51	2024-09-25 10:49:38	HAZARD	Avenue	Cautionary Signs	30.378160833	76.734825333	7256.135560482	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0006 (1)_1518.jpg
52	2024-09-25 10:50:01	CHEVRON	Median	Cautionary Signs	30.376481667	76.7348005	7442.85840604	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0006 (1)_2204.jpg

53	2024-09-25 10:51:39	INFORMATORY_ SIGNS	Median	Informatory Signs	30.3698005	76.734694333	8185.0081687	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0006 (1)_5154.jpg
54	2024-09-25 10:52:27	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.366497333	76.7344385	8553.138071052	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0007_117 3.jpg
55	2024-09-25 10:53:05	INFORMATORY_ SIGNS	Median	Informatory Signs	30.3636895	76.734087833	8866.456166243	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0007_233 5.jpg
56	2024-09-25 10:53:14	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.363039667	76.734005167	8938.753150182	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0007_260 4.jpg

57	2024-09-25 10:53:39	HAZARD	Median	Cautionary Signs	30.361434	76.733811667	9106.644274731	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_10.png
58	2024-09-25 10:53:39	PROHIBITORY_M ANDATORY_SIG NS	Avenue	Mandatory Signs	30.361434	76.733811667	9106.644274731	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_10.png
59	2024-09-25 10:54:22	PROHIBITORY_M ANDATORY_SIG NS	Median	Mandatory Signs	30.358473167	76.7333305	9448.527909963	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0007_463 0.jpg
60	2024-09-25 10:55:27	INFORMATORY_ SIGNS	Overhead	Informatory Signs	30.353997333	76.732320833	9944.379746441	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_11.png
61	2024-09-25 10:56:20	CHEVRON	Avenue	Cautionary Signs	30.350503833	76.731461	10351.0891521	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0008_280 7.jpg

62	2024-09-25 10:57:04	PROHIBITORY_M ANDATORY_SIG NS		Mandatory Signs	30.347333167	76.730453167	10715.80804631	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0008_413 9.jpg
63	2024-09-25 10:57:09	CHEVRON	Median	Cautionary Signs	30.346995667	76.7303415	10753.99195568	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0008_427 8.jpg
64	2024-09-25 10:57:13	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.346741667	76.7302545	10783.07769481	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0008_438 2.jpg
65	2024-09-25 10:57:25	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.346030833	76.730036167	10863.38024949	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0008_475 8.jpg

66	2024-09-25 10:58:01	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.344088167	76.729359333	11081.35815874	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_12.png
67	2024-09-25 10:58:28	CHEVRON	Median	Cautionary Signs	30.342247	76.7289065	11302.04508435	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0009_125 6.jpg
68	2024-09-25 10:58:51	HAZARD	Avenue	Cautionary Signs	30.3405435	76.729164333	11493.33194781	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0009_194 9.jpg
69	2024-09-25 11:00:10	PROHIBITORY_M ANDATORY_SIG NS	Avenue	Mandatory Signs	30.3350335	76.727751333	12145.75229489	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0009_429 3.jpg

70	2024-09-25 11:01:47	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.328387167	76.724209167	12957.45710727	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0010_181 3.jpg
71	2024-09-25 11:01:50	INFORMATORY_ SIGNS	Median	Informatory Signs	30.328178833	76.724096833	12972.91380267	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_13.png
72	2024-09-25 11:01:58	HAZARD	Median	Cautionary Signs	30.327640167	76.723812333	13047.28694037	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0010_215 7.jpg
73	2024-09-25 11:02:14	CHEVRON	Median	Cautionary Signs	30.326713333	76.723325	13160.90394061	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0010_261 1.jpg

74	2024-09-25 11:03:16	CHEVRON	Median	Cautionary Signs	30.322332333	76.722233	13661.79769971	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0010_449 1.jpg
75	2024-09-25 11:03:25	PROHIBITORY_M ANDATORY_SIG NS	Avenue	Mandatory Signs	30.321735833	76.722164833	13726.98485771	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0010_475 8.jpg
76	2024-09-25 11:06:28	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.310795833	76.721805	14942.40535341	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0011_483 5.jpg
77	2024-09-25 11:06:29	CHEVRON	Median	Cautionary Signs	30.310727667	76.721803167	14949.94505721	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0011_488 4.jpg

78	2024-09-25 11:06:38	CHEVRON	Median	Cautionary Signs	30.310121333	76.721794333	15006.51983009	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_14.png
79	2024-09-25 11:06:49	CHEVRON	Median	Cautionary Signs	30.309431667	76.72182	15093.04096383	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0012_81.j pg
80	2024-09-25 11:07:06	CHEVRON	Median	Cautionary Signs	30.308297167	76.722102667	15223.36961543	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0012_585. jpg
81	2024-09-25 11:07:24	CHEVRON	Avenue	Cautionary Signs	30.307142667	76.722505167	15355.39374738	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0012_113 3.jpg

82	2024-09-25 11:07:43	CHEVRON	Avenue	Cautionary Signs	30.305890333	76.7226155	15496.17238034	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0012_169 2.jpg
83	2024-09-25 11:07:51	CHEVRON	Avenue	Cautionary Signs	30.305340333	76.72252	15558.04286691	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0012_192 7.jpg
84	2024-09-25 11:07:52	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.305271167	76.722502667	15565.9612131	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0012_196 0.jpg
85	2024-09-25 11:07:56	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.304992667	76.722422167	15597.88519127	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0012_207 3.jpg

		1		1				
86	2024-09-25 11:07:59	CHEVRON	Avenue	Cautionary Signs	30.3047815	76.7223555	15622.45427928	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0012_216 1.jpg
87	2024-09-25 11:08:59	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.300354333	76.720850333	16123.40395043	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_15.png
88	2024-09-25 11:09:27	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.298498333	76.720220667	16337.51658123	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_16.png
89	2024-09-25 11:11:21	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.290780833	76.7175355	17241.89531613	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_283 1.jpg
90	2024-09-25 11:11:36	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.289741167	76.717173667	17362.75370845	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_328 3.jpg

91	2024-09-25 11:11:37	CHEVRON	Avenue	Cautionary Signs	30.289669333	76.717148833	17371.07164379	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_330 9.jpg
92	2024-09-25 11:11:42	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.289316833	76.717028167	17401.31760219	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_17.png
93	2024-09-25 11:11:42	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.289316833	76.717028167	17401.31760219	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_18.png
94	2024-09-25 11:11:42	HAZARD	Median	Cautionary Signs	30.289316833	76.717028167	17411.31760219	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_345 7.jpg
95	2024-09-25 11:11:42	PROHIBITORY_M ANDATORY_SIG NS	Median	Mandatory Signs	30.289316833	76.717028167	17421.31760219	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_345 7.jpg

1								
96	2024-09-25 11:11:44	CHEVRON	Median	Cautionary Signs	30.289182667	76.716983167	17426.65726535	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_353 3.jpg
97	2024-09-25 11:11:49	CHEVRON	Median	Cautionary Signs	30.288841	76.716877333	17466.43749626	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_366 6.jpg
98	2024-09-25 11:11:55	CHEVRON	Median	Cautionary Signs	30.288397333	76.716778167	17506.81519635	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_50.png
99	2024-09-25 11:11:55	CHEVRON	Avenue	Cautionary Signs	30.288397333	76.716778167	17506.81519635	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_51.png
100	2024-09-25 11:11:56	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.288321667	76.716767167	17525.23467707	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_387 4.jpg

101	2024-09-25 11:11:58	INFORMATORY_ SIGNS	Median	Informatory Signs	30.288169667	76.716751333	17532.24644102	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_19.png
102	2024-09-25 11:12:01	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.287938833	76.716741167	17567.79024966	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_402 0.jpg
103	2024-09-25 11:12:01	CHEVRON	Median	Cautionary Signs	30.287938833	76.716741167	17567.79024966	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_403 1.jpg
104	2024-09-25 11:12:03	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.287786167	76.7167415	17584.80977043	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_408 8.jpg

105	2024-09-25 11:12:06	CHEVRON	Median	Cautionary Signs	30.287553833	76.716756333	17610.77676356	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_419 5.jpg
106	2024-09-25 11:12:08	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.287398	76.7167815	17628.32881856	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_423 4.jpg
107	2024-09-25 11:12:11	CHEVRON	Median	Cautionary Signs	30.287164833	76.716835	17654.60722597	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_433 7.jpg
108	2024-09-25 11:12:19	CHEVRON	Median	Cautionary Signs	30.286570167	76.717064	17723.7788708	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_457 8.jpg

			1					
109	2024-09-25 11:12:26	HAZARD	Median	Cautionary Signs	30.2860925	76.7173165	17782.06652331	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_477 9.jpg
110	2024-09-25 11:12:27	CHEVRON	Median	Cautionary Signs	30.286024167	76.717353333	17790.33923574	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_480 2.jpg
111	2024-09-25 11:12:28	CHEVRON	Median	Cautionary Signs	30.285956667	76.71739	17798.56871095	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_485 6.jpg
112	2024-09-25 11:12:29	CHEVRON	Median	Cautionary Signs	30.285889667	76.717426833	17806.75799252	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_488 8.jpg

	T	,		T		T	ı	
113	2024-09-25 11:12:39	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.285273333	76.7177795	17881.48814066	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0013_517 4.jpg
114	2024-09-25 11:12:56	CHEVRON	Avenue	Cautionary Signs	30.284464167	76.718328	17986.00265283	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_294. jpg
115	2024-09-25 11:13:08	CHEVRON	Avenue	Cautionary Signs	30.283775333	76.718615667	18067.13477696	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_644. jpg
116	2024-09-25 11:13:16	CHEVRON	Avenue	Cautionary Signs	30.283263	76.718713833	18125.54737983	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_883. jpg

117	2024-09-25 11:13:28	CHEVRON	Avenue	Cautionary Signs	30.2824465	76.718744667	18216.26808536	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_123 2.jpg
118	2024-09-25 11:13:46	PROHIBITORY_M ANDATORY_SIG NS	Avenue	Mandatory Signs	30.281357833	76.718698	18336.31848729	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_179 8.jpg
119	2024-09-25 11:13:49	CHEVRON	Median	Cautionary Signs	30.281168333	76.718693833	18347.5147269	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_20.png
120	2024-09-25 11:14:10	CHEVRON	Avenue	Cautionary Signs	30.279932167	76.718657333	18494.41736174	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_251 7.jpg

121	2024-09-25 11:14:26	CHEVRON	Avenue	Cautionary Signs	30.2789955	76.718604667	18597.98066918	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_297 6.jpg
122	2024-09-25 11:14:29	HAZARD	Median	Cautionary Signs	30.278824833	76.718579167	18617.09060332	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_308 7.jpg
123	2024-09-25 11:14:33	CHEVRON	Avenue	Cautionary Signs	30.278593	76.718534833	18643.31450287	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_320 8.jpg
124	2024-09-25 11:14:41	CHEVRON	Avenue	Cautionary Signs	30.278133667	76.718410333	18695.61626187	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_342 8.jpg

125	2024-09-25 11:14:48	CHEVRON	Avenue	Cautionary Signs	30.2777465	76.718231167	18742.02175744	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_364 5.jpg
126	2024-09-25 11:15:03	CHEVRON	Avenue	Cautionary Signs	30.276998	76.717681167	18841.35292598	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_410 7.jpg
127	2024-09-25 11:15:10	CHEVRON	Avenue	Cautionary Signs	30.276637333	76.717336333	18893.44305697	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_429 1.jpg
128	2024-09-25 11:15:41	PROHIBITORY_M ANDATORY_SIG NS		Mandatory Signs	30.275275667	76.715861833	19100.15711432	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_522 1.jpg

129	2024-09-25 11:15:41	CHEVRON	Median	Cautionary Signs	30.275275667	76.715861833	19100.15711432	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_524 6.jpg
130	2024-09-25 11:15:44	PROHIBITORY_M ANDATORY_SIG NS	Avenue	Mandatory Signs	30.275158333	76.715704333	19110.33368075	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_21.png
131	2024-09-25 11:15:43	CHEVRON	Median	Cautionary Signs	30.275201167	76.7157545	19113.56505267	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_529 3.jpg
132	2024-09-25 11:15:44	HAZARD	Avenue	Cautionary Signs	30.275158333	76.715704333	19120.33368075	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0014_531 9.jpg

133	2024-09-25 11:15:52	HAZARD	Median	Cautionary Signs	30.274786	76.715317833	19176.39282059	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0015_151. jpg
134	2024-09-25 11:16:31	CHEVRON	Avenue	Cautionary Signs	30.272649833	76.714353	19423.01041359	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_22.png
135	2024-09-25 11:16:31	CHEVRON	Avenue	Cautionary Signs	30.272649833	76.714353	19433.01041359	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0015_134 3.jpg
136	2024-09-25 11:19:18	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.260953167	76.712615667	20743.69165076	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0016_971. jpg

137	2024-09-25 11:19:28	HAZARD	Median	Cautionary Signs	30.260182667	76.712507	20828.81241117	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0016_128 6.jpg
138	2024-09-25 11:22:59	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.244051167	76.709321333	22647.31980479	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0017_217 5.jpg
139	2024-09-25 11:23:12	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.242874667	76.709064833	22779.21294887	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0017_256 4.jpg
140	2024-09-25 11:24:53	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.234498	76.706984333	23718.42981728	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_23.png

141	2024-09-25 11:26:43	CHEVRON	Avenue	Cautionary Signs	30.2267815	76.707208833	24586.45776765	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0018_350 8.jpg
142	2024-09-25 11:26:51	CHEVRON	Avenue	Cautionary Signs	30.2261945	76.707100667	24652.14883975	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0018_373 3.jpg
143	2024-09-25 11:27:43	HAZARD	Avenue	Cautionary Signs	30.222520167	76.706402333	25064.46248575	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0018_528 8.jpg
144	2024-09-25 11:27:48	CHEVRON	Median	Cautionary Signs	30.222178833	76.706333167	25103.10965836	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0019_30.j pg

145	2024-09-25 11:27:57	CHEVRON	Median	Cautionary Signs	30.221562833	76.7062135	25162.12089131	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_24.png
146	2024-09-25 11:28:06	CHEVRON	Median	Cautionary Signs	30.220960333	76.706138833	25238.92039347	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0019_596. jpg
147	2024-09-25 11:28:13	CHEVRON	Median	Cautionary Signs	30.220508667	76.706135	25288.8186464	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0019_783. jpg
148	2024-09-25 11:28:20	CHEVRON	Median	Cautionary Signs	30.220079667	76.706180167	25336.54350856	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0019_993. jpg

149	2024-09-25 11:28:26	CHEVRON	Median	Cautionary Signs	30.219706167	76.706269333	25379.30746027	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0019_119 3.jpg
150	2024-09-25 11:28:35	HAZARD	Avenue	Cautionary Signs	30.219110167	76.706452833	25448.10969188	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0019_146 9.jpg
151	2024-09-25 11:28:59	INFORMATORY_ SIGNS	Overhead	Informatory Signs	30.217288667	76.707014833	25647.52871626	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_25.png
152	2024-09-25 11:29:46	CHEVRON	Avenue	Cautionary Signs	30.214163333	76.707940667	26014.46469315	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0019_358 5.jpg

153	2024-09-25 11:29:54	CHEVRON	Avenue	Cautionary Signs	30.213645667	76.707987833	26072.57811416	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0019_383 1.jpg
154	2024-09-25 11:30:14	CHEVRON	Avenue	Cautionary Signs	30.2123835	76.707124167	26230.84121653	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_26.png
155	2024-09-25 11:30:19	CHEVRON	Avenue	Cautionary Signs	30.212153167	76.7067875	26282.95538833	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0019_457 9.jpg
156	2024-09-25 11:30:58	CHEVRON	Median	Cautionary Signs	30.210033	76.704167167	26628.27258715	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_352. jpg

157	2024-09-25 11:31:07	CHEVRON	Median	Cautionary Signs	30.209524	76.703633333	26704.77847	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_626. jpg
158	2024-09-25 11:31:16	CHEVRON	Median	Cautionary Signs	30.2089645	76.703120167	26784.19226486	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_887. jpg
159	2024-09-25 11:31:25	CHEVRON	Median	Cautionary Signs	30.208392667	76.7027335	26856.9838295	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_115 3.jpg
160	2024-09-25 11:31:36	CHEVRON	Median	Cautionary Signs	30.2076335	76.702417667	26936.79313224	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_27.png

161	2024-09-25 11:31:46	HAZARD	Median	Cautionary Signs	30.206913167	76.702282667	27027.75658455	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_179 9.jpg
162	2024-09-25 11:31:55	CHEVRON	Median	Cautionary Signs	30.206237667	76.7022985	27103.53420198	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_204 5.jpg
163	2024-09-25 11:31:58	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.205997333	76.702334167	27120.62440502	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_52.png
164	2024-09-25 11:32:00	CHEVRON	Median	Cautionary Signs	30.205833333	76.702367833	27149.46021341	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_220 3.jpg

165	2024-09-25 11:32:08	CHEVRON	Median	Cautionary Signs	30.205177167	76.702571667	27224.4592407	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_244 4.jpg
166	2024-09-25 11:32:57	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.201602333	76.703933	27641.23013744	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_392 6.jpg
167	2024-09-25 11:32:59	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.201457333	76.703989	27658.10440379	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_397 9.jpg
168	2024-09-25 11:33:01	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.201314	76.704044167	27664.751104	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_28.png

169	2024-09-25 11:33:05	PROHIBITORY_M ANDATORY_SIG NS	Avenue	Mandatory Signs	30.201034333	76.704159833	27707.35740688	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_416 4.jpg
170	2024-09-25 11:33:06	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.200966833	76.704188333	27715.30956732	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_417 9.jpg
171	2024-09-25 11:33:08	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.2008325	76.704246667	27731.34660218	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_423 2.jpg
172	2024-09-25 11:33:12	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.200552833	76.704366	27754.90439457	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_29.png
173	2024-09-25 11:33:16	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.2002625	76.704495167	27789.61130692	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_30.png

174	2024-09-25 11:33:16	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.2002625	76.704495167	27799.61130692	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_448 4.jpg
175	2024-09-25 11:33:17	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.200189	76.704528833	27808.44462095	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_452 6.jpg
176	2024-09-25 11:33:22	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.199815833	76.7047045	27853.35688442	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_467 8.jpg
177	2024-09-25 11:33:24	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.199664667	76.704776333	27871.50919387	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_473 7.jpg

178	2024-09-25 11:33:27	CHEVRON	Avenue	Cautionary Signs	30.199437667	76.704884	27898.66203121	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_482 7.jpg
179	2024-09-25 11:33:36	CHEVRON	Avenue	Cautionary Signs	30.198791	76.705189667	27975.11390084	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0020_508 0.jpg
180	2024-09-25 11:33:48	CHEVRON	Avenue	Cautionary Signs	30.198073	76.705489667	28058.27146723	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0021_48.j pg
181	2024-09-25 11:33:53	INFORMATORY_ SIGNS	Median	Informatory Signs	30.197814333	76.7056075	28088.79621616	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0021_193. jpg

182	2024-09-25 11:33:54	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.197763	76.705631167	28095.00601784	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0021_221. jpg
183	2024-09-25 11:34:00	INFORMATORY_ SIGNS	Overhead	Informatory Signs	30.197439	76.705745667	28122.26659201	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_31.png
184	2024-09-25 11:34:39	CHEVRON	Avenue	Cautionary Signs	30.1965	76.705851833	28237.38463498	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0021_158 5.jpg
185	2024-09-25 11:34:50	CHEVRON	Avenue	Cautionary Signs	30.195843333	76.705873167	28311.30058661	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0021_190 1.jpg

186	2024-09-25 11:34:57	HAZARD	Median	Cautionary Signs	30.195449833	76.705890833	28354.43592595	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0021_211 6.jpg
187	2024-09-25 11:35:03	CHEVRON	Avenue	Cautionary Signs	30.195096833	76.7058945	28394.19742065	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0021_230 7.jpg
188	2024-09-25 11:35:24	CHEVRON	Avenue	Cautionary Signs	30.193782667	76.705740833	28540.49921456	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0021_291 2.jpg
189	2024-09-25 11:35:29	HAZARD	Avenue	Cautionary Signs	30.1934995	76.705669833	28572.20516462	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0021_306 5.jpg

190	2024-09-25 11:38:59	CHEVRON	Median	Cautionary Signs	30.179154167	76.698667333	30302.69676909	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0022_398 7.jpg
191	2024-09-25 11:39:32	HAZARD	Median	Cautionary Signs	30.1771945	76.697745833	30535.57053159	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0022_495 6.jpg
192	2024-09-25 11:39:42	CHEVRON	Avenue	Cautionary Signs	30.176689667	76.697553333	30595.20054901	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0022_525 4.jpg
193	2024-09-25 11:39:54	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.175994	76.697083833	30687.14901007	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0023_227. jpg

194	2024-09-25 11:40:42	PROHIBITORY_M ANDATORY_SIG NS	Median	Mandatory Signs	30.172634833	76.695318	31096.40078756	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0023_165 4.jpg
195	2024-09-25 11:40:45	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.172436667	76.695218667	31109.92180052	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_33.png
196	2024-09-25 11:40:48	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.172247667	76.695128667	31142.11876902	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0023_184 1.jpg
197	2024-09-25 11:41:22	CHEVRON	Median	Cautionary Signs	30.170272333	76.694257333	31377.31900487	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0023_287 5.jpg

198	2024-09-25 11:41:29	INFORMATORY_ SIGNS	Median	Informatory Signs	30.169875167	76.6940395	31426.54367231	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0023_307 6.jpg
199	2024-09-25 11:41:40	HAZARD	Median	Cautionary Signs	30.169229833	76.693796	31501.56905168	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0023_339 9.jpg
200	2024-09-25 11:44:21	PROHIBITORY_M ANDATORY_SIG NS	Median	Mandatory Signs	30.158798833	76.688573833	32766.14940913	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0024_282 2.jpg
201	2024-09-25 11:44:44	HAZARD	Median	Cautionary Signs	30.157172833	76.687772333	32962.17564214	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0024_353 1.jpg

202	2024-09-25 11:45:29	CHEVRON	Median	Cautionary Signs	30.153997667	76.686223167	33343.52684068	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0024_488 0.jpg
203	2024-09-25 11:45:40	INFORMATORY_ SIGNS	Median	Informatory Signs	30.153283833	76.685872	33429.67021805	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0024_519 2.jpg
204	2024-09-25 11:45:43	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.153096	76.685783167	33451.8421027	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0024_528 5.jpg
205	2024-09-25 11:45:47	PROHIBITORY_M ANDATORY_SIG NS	Avenue	Mandatory Signs	30.152858167	76.685678	33479.07142766	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0025_7.jpg

2	06	2024-09-25 11:45:50	HAZARD	Median	Cautionary Signs	30.152703167	76.685628	33496.08736348	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0025_96.j pg
2	07	2024-09-25 11:46:17	PROHIBITORY_M ANDATORY_SIG NS		Mandatory Signs	30.151238333	76.684969833	33672.34678054	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0025_915. jp8
2	08	2024-09-25 11:46:43	PROHIBITORY_M ANDATORY_SIG NS		Mandatory Signs	30.149783333	76.684274167	33846.82733797	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0025_170 5.jpg
2	09	2024-09-25 11:48:59	CHEVRON	Median	Cautionary Signs	30.140718667	76.6796435	34949.00771519	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0026_388. jpg

210	2024-09-25 11:49:03	INFORMATORY_ SIGNS	Median	Informatory Signs	30.140430833	76.6795185	34973.12616701	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_34.png
211	2024-09-25 11:49:11	CHEVRON	Median	Cautionary Signs	30.139809	76.679285333	35056.36139332	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0026_731. jpg
212	2024-09-25 11:49:16	CHEVRON	Median	Cautionary Signs	30.139392667	76.679166333	35103.85382526	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0026_893. jpg
213	2024-09-25 11:49:17	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.139310167	76.679145167	35113.08393694	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0026_923. jpg
214	2024-09-25 11:49:19	INFORMATORY_ SIGNS	Median	Informatory Signs	30.139148	76.6791095	35121.03077847	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_35.png

215	2024-09-25 11:49:19	INFORMATORY_ SIGNS	Median	Informatory Signs	30.139148	76.6791095	35131.03077847	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0026_960. jpg
216	2024-09-25 11:49:25	INFORMATORY_ SIGNS	Median	Informatory Signs	30.1386825	76.679029667	35173.12965676	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_36.png
217	2024-09-25 11:49:24	HAZARD	Median	Cautionary Signs	30.138760333	76.679040833	35174.33768585	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0026_113 7.jpg
218	2024-09-25 11:49:33	CHEVRON	Median	Cautionary Signs	30.138048333	76.678975333	35243.33471848	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_37.png
219	2024-09-25 11:49:34	HAZARD	Avenue	Cautionary Signs	30.137971833	76.678972	35261.80049666	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0026_142 6.jpg

220	2024-09-25 11:49:44	HAZARD	Avenue	Cautionary Signs	30.137215	76.678964333	35345.4280308	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0026_173 5.jpg
221	2024-09-25 11:51:26	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.129549167	76.679194	36195.63355719	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0026_477 5.jpg
222	2024-09-25 11:51:32	INFORMATORY_ SIGNS	Overhead	Informatory Signs	30.129144333	76.6792525	36230.40159626	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_38.png
223	2024-09-25 11:51:48	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.128067333	76.679408167	36361.11612771	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0027_54.j pg

224	2024-09-25 11:52:35	HAZARD	Avenue	Cautionary Signs	30.124594833	76.679387333	36746.16845118	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0027_145 0.jpg
225	2024-09-25 11:53:23	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.121057	76.679403667	37128.85721315	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_53.png
226	2024-09-25 11:53:33	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.1203245	76.679394833	37220.19175279	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0027_318 2.jpg
227	2024-09-25 11:55:59	CHEVRON	Avenue	Cautionary Signs	30.109947833	76.678223667	38388.81143919	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0028_217 1.jpg

								,
228	2024-09-25 11:56:01	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.109817667	76.678134333	38405.80901029	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0028_224 4.jpg
229	2024-09-25 11:56:09	CHEVRON	Avenue	Cautionary Signs	30.109358333	76.677781	38465.61402631	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0028_248 2.jpg
230	2024-09-25 11:56:17	CHEVRON	Avenue	Cautionary Signs	30.108937167	76.6774065	38525.37443498	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0028_270 8.jpg
231	2024-09-25 11:56:23	CHEVRON	Avenue	Cautionary Signs	30.108632667	76.677078833	38571.48860909	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0028_290 0.jpg

232	2024-09-25 11:56:31	CHEVRON	Avenue	Cautionary Signs	30.108271	76.676639	38629.59751625	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0028_313 7.jpg
233	2024-09-25 11:56:41	CHEVRON	Avenue	Cautionary Signs	30.107848833	76.676029	38704.80549408	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0028_343 1.jpg
234	2024-09-25 11:56:50	CHEVRON	Avenue	Cautionary Signs	30.107520333	76.675447333	38772.0723995	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0028_369 8.jpg
235	2024-09-25 11:56:59	CHEVRON	Avenue	Cautionary Signs	30.1072175	76.674782667	38844.70737071	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0028_397 1.jpg

236	2024-09-25 11:57:09	CHEVRON	Avenue	Cautionary Signs	30.10695	76.6740255	38923.25384786	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0028_428 5.jpg
237	2024-09-25 11:57:26	CHEVRON	Median	Cautionary Signs	30.106590167	76.672641	39062.9458672	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0028_477 2.jpg
238	2024-09-25 11:57:40	CHEVRON	Median	Cautionary Signs	30.106274167	76.671485167	39180.08112925	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0028_519 9.jpg
239	2024-09-25 11:57:48	CHEVRON	Median	Cautionary Signs	30.1060215	76.670845833	39247.81801079	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0029_38.j pg

1								,
240	2024-09-25 11:57:58	CHEVRON	Median	Cautionary Signs	30.1056165	76.670102	39332.16938211	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0029_338. jpg
241	2024-09-25 11:58:10	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.105054	76.669340833	39428.37336729	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0029_698. jpg
242	2024-09-25 11:58:11	HAZARD	Avenue	Cautionary Signs	30.105001833	76.669282667	39436.45509034	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0029_734. jpg
243	2024-09-25 11:58:16	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.1047245	76.669003833	39477.48960764	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0029_892. jpg

244	2024-09-25 11:58:18	CHEVRON	Median	Cautionary Signs	30.104606667	76.668896167	39484.43043454	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_54.png
245	2024-09-25 11:58:38	HAZARD	Avenue	Cautionary Signs	30.1032665	76.6680055	39666.66357839	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0029_153 9.jpg
246	2024-09-25 11:58:41	CHEVRON	Median	Cautionary Signs	30.103056	76.6679175	39691.05044743	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0029_164 6.jpg
247	2024-09-25 11:58:45	HAZARD	Median	Cautionary Signs	30.102777167	76.667816333	39713.70244659	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_39.png
248	2024-09-25 11:59:06	CHEVRON	Median	Cautionary Signs	30.101248167	76.667570833	39885.62265848	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_55.png

249	2024-09-25 12:00:12	HAZARD	Avenue	Cautionary Signs	30.096204333	76.667488333	40454.75678919	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0029_435 4.jpg
250	2024-09-25 12:00:41	HAZARD	Avenue	Cautionary Signs	30.093884	76.6674565	40712.38171327	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0029_522 8.jpg
251	2024-09-25 12:01:35	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.089615667	76.667406667	41185.77240751	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0030_145 8.jpg
252	2024-09-25 12:01:51	HAZARD	Median	Cautionary Signs	30.088326333	76.667411667	41318.3883807	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_40.png

253	2024-09-25 12:02:09	HAZARD	Avenue	Cautionary Signs	30.086828333	76.6673855	41494.84621241	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0030_248 9.jpg
254	2024-09-25 12:02:51	CHEVRON	Median	Cautionary Signs	30.0836635	76.667343	41845.61844435	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0030_373 5.jpg
255	2024-09-25 12:03:08	CHEVRON	Median	Cautionary Signs	30.082480167	76.667358	41973.73497963	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0030_423 4.jpg
256	2024-09-25 12:03:09	HAZARD	Median	Cautionary Signs	30.082428667	76.6673715	41979.58598222	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0030_426 1.jpg

257	2024-09-25 12:03:29	CHEVRON	Median	Cautionary Signs	30.081218833	76.667427	42115.4335045	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0030_486 6.jpg
258	2024-09-25 12:03:37	CHEVRON	Median	Cautionary Signs	30.080714667	76.667475333	42171.73403522	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0030_510 6.jpg
259	2024-09-25 12:03:46	CHEVRON	Median	Cautionary Signs	30.0801855	76.667620167	42231.79978826	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0030_537 3.jpg
260	2024-09-25 12:03:51	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.079899667	76.667756833	42266.31680201	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0031_145. jpg

261	2024-09-25 12:04:05	CHEVRON	Avenue	Cautionary Signs	30.079176167	76.668205	42357.42406012	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0031_544. jpg
262	2024-09-25 12:04:11	CHEVRON	Avenue	Cautionary Signs	30.078852333	76.668411333	42398.00922674	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0031_734. jpg
263	2024-09-25 12:04:23	CHEVRON	Avenue	Cautionary Signs	30.078204833	76.668846167	42481.39421064	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0031_109 1.jpg
264	2024-09-25 12:05:02	CHEVRON	Avenue	Cautionary Signs	30.075663167	76.669675	42769.3546988	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_41.png

265	2024-09-25 12:05:29	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.0736025	76.6697535	43007.58151242	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0031_308 2.jpg
266	2024-09-25 12:05:32	CHEVRON	Avenue	Cautionary Signs	30.0733705	76.669753333	43033.46973946	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0031_315 7.jpg
267	2024-09-25 12:05:51	HAZARD	Median	Cautionary Signs	30.071978667	76.669423833	43192.54952372	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0031_373 4.jpg
268	2024-09-25 12:05:56	CHEVRON	Avenue	Cautionary Signs	30.071615167	76.669207167	43228.45632882	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_42.png
269	2024-09-25 12:06:02	CHEVRON	Avenue	Cautionary Signs	30.071192333	76.668881833	43284.62689224	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_56.png

		1		1		1		
270	2024-09-25 12:06:08	CHEVRON	Avenue	Cautionary Signs	30.070825	76.668540667	43346.28687029	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0031_424 3.jpg
271	2024-09-25 12:06:11	HAZARD	Median	Cautionary Signs	30.070661667	76.668360667	43371.19253392	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0031_434 1.jpg
272	2024-09-25 12:06:43	INFORMATORY_ SIGNS	Median	Informatory Signs	30.069082	76.666231833	43631.26233579	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_43.png
273	2024-09-25 12:08:44	PROHIBITORY_M ANDATORY_SIG NS	Avenue	Mandatory Signs	30.0631735	76.658133333	44650.58562506	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_44.png
274	2024-09-25 12:10:09	PROHIBITORY_M ANDATORY_SIG NS	Median	Mandatory Signs	30.059096667	76.652268	45385.07215096	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_664. jpg

275	2024-09-25 12:10:10	HAZARD	Avenue	Cautionary Signs	30.059045833	76.652196167	45393.84436883	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_699. jpg
276	2024-09-25 12:10:13	INFORMATORY_ SIGNS	Median	Informatory Signs	30.0589015	76.651992167	45418.26369724	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_797. jpg
277	2024-09-25 12:10:14	HAZARD	Median	Cautionary Signs	30.058856167	76.651929833	45425.69699687	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_826. jpg
278	2024-09-25 12:10:20	INFORMATORY_ SIGNS	Median	Informatory Signs	30.058624333	76.651620167	45453.48207026	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_45.png

279	2024-09-25 12:10:22	INFORMATORY_ SIGNS	Median	Informatory Signs	30.058555667	76.6515315	45474.60329871	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_106 7.jpg
280	2024-09-25 12:10:29	INFORMATORY_ SIGNS	Overhead	Informatory Signs	30.058328	76.651248	45500.93942234	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_57.png
281	2024-09-25 12:10:34	PROHIBITORY_M ANDATORY_SIG NS	Median	Mandatory Signs	30.058188333	76.651097	45532.04282816	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_143 4.jpg
282	2024-09-25 12:10:35	INFORMATORY_ SIGNS	Median	Informatory Signs	30.058155333	76.651071	45536.66451923	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_146 4.jpg

283	2024-09-25 12:10:36	CHEVRON	Median	Cautionary Signs	30.0581195	76.6510465	45541.24379423	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_148 3.jpg
284	2024-09-25 12:10:47	CHEVRON	Median	Cautionary Signs	30.057909	76.6509395	45563.9428971	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_181 5.jpg
285	2024-09-25 12:10:52	CHEVRON	Median	Cautionary Signs	30.057795333	76.650917833	45578.89215108	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_196 1.jpg
286	2024-09-25 12:10:56	CHEVRON	Median	Cautionary Signs	30.057648333	76.650922667	45595.54840732	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_208 4.jpg

287	2024-09-25 12:10:58	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.057572333	76.650932833	45604.0553696	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_213 1.jpg
288	2024-09-25 12:11:00	CHEVRON	Median	Cautionary Signs	30.057497667	76.650947	45612.22140205	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_220 1.jpg
289	2024-09-25 12:11:03	CHEVRON	Avenue	Cautionary Signs	30.057385833	76.650969667	45625.44751271	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_230 6.jpg
290	2024-09-25 12:11:07	CHEVRON	Avenue	Cautionary Signs	30.057205	76.6510025	45647.1177762	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_241 4.jpg

291	2024-09-25 12:11:10	CHEVRON	Avenue	Cautionary Signs	30.057034167	76.651030833	45667.10180943	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_250 6.jpg
292	2024-09-25 12:11:13	CHEVRON	Avenue	Cautionary Signs	30.056845833	76.651054333	45688.30370355	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_258 6.jpg
293	2024-09-25 12:11:15	CHEVRON	Avenue	Cautionary Signs	30.056718333	76.651052333	45702.53311092	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_266 6.jpg
294	2024-09-25 12:11:18	CHEVRON	Avenue	Cautionary Signs	30.056529833	76.6510045	45723.72689853	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_274 6.jpg

		,		1				
295	2024-09-25 12:11:21	CHEVRON	Avenue	Cautionary Signs	30.056358667	76.650918333	45744.48263504	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_283 2.jpg
296	2024-09-25 12:11:24	CHEVRON	Avenue	Cautionary Signs	30.056206333	76.650793167	45765.34463757	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_291 2.jpg
297	2024-09-25 12:11:26	CHEVRON	Avenue	Cautionary Signs	30.056119333	76.650686167	45779.78139424	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_298 9.jpg
298	2024-09-25 12:11:27	PROHIBITORY_M ANDATORY_SIG NS	Avenue	Mandatory Signs	30.056079833	76.650625667	45787.23924216	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_302 9.jpg

								,
299	2024-09-25 12:11:29	CHEVRON	Avenue	Cautionary Signs	30.056012333	76.650490833	45802.39520509	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_306 3.jpg
300	2024-09-25 12:11:38	PROHIBITORY_M ANDATORY_SIG NS	Avenue	Mandatory Signs	30.055905667	76.649802833	45870.25642619	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_335 7.jpg
301	2024-09-25 12:11:59	CHEVRON	Median	Cautionary Signs	30.055795667	76.648157833	46028.96940181	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_396 8.jpg
302	2024-09-25 12:12:02	CHEVRON	Median	Cautionary Signs	30.055771333	76.647932167	46051.01802709	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_405 8.jpg

	T	1		1			T	
303	2024-09-25 12:12:03	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.0557605	76.6478565	46058.48367176	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_408 2.jpg
304	2024-09-25 12:12:05	CHEVRON	Median	Cautionary Signs	30.055732833	76.647704	46073.65787139	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_414 7.jpg
305	2024-09-25 12:12:15	HAZARD	Median	Cautionary Signs	30.055486667	76.646935667	46153.25917057	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0033_445 0.jpg
306	2024-09-25 12:15:47	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.044883167	76.632011167	48016.59601148	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0035_50.j pg

307	2024-09-25 12:15:50	INFORMATORY_ SIGNS	Median	Informatory Signs	30.0446825	76.631856	48033.14108141	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_46.png
308	2024-09-25 12:15:55	HAZARD	Median	Cautionary Signs	30.044362667	76.631602833	48085.88008341	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0035_274. jpg
309	2024-09-25 12:16:41	INFORMATORY_ SIGNS	Avenue	Informatory Signs	30.041465833	76.629443833	48458.28471552	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_47.png
310	2024-09-25 12:17:02	HAZARD	Median	Cautionary Signs	30.040156833	76.628463833	48632.34813389	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_58.png
311	2024-09-25 12:19:57	CHEVRON	Avenue	Cautionary Signs	30.029468333	76.6204075	50059.71395983	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0036_215 9.jpg

	1			1		Γ		
312	2024-09-25 12:20:03	CHEVRON	Avenue	Cautionary Signs	30.029107833	76.6200085	50115.43037129	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0036_233 9.jpg
313	2024-09-25 12:20:07	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.028875167	76.619729333	50152.30423211	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0036_244 3.jpg
314	2024-09-25 12:20:12	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.028603833	76.6193965	50186.04740127	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_48.png
315	2024-09-25 12:20:18	HAZARD	Median	Cautionary Signs	30.028287667	76.618996333	50238.18566387	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/ frame_49.png
316	2024-09-25 12:20:50	CAUTIONARY_W ARNING_SIGNS	Avenue	Cautionary Signs	30.026569333	76.616808667	50532.43359254	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0036_373 1.jpg

317	2024-09-25 12:21:22	CAUTIONARY_W ARNING_SIGNS	Median	Cautionary Signs	30.024988333	76.6148205	50792.29835541	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0036_468 9.jpg
318	2024-09-25 12:21:57	INFORMATORY_ SIGNS	Median	Informatory Signs	30.023263667	76.612727667	51066.19629457	https:// raiotransection.s 3.ap- south-1.amazona ws.com/ furniture/ output/frames/ survey_1/ road_1/assets/ NORM0037_333. jpg