

PO Allomeric Function

notice: Api calls must be one by one ,when the end of an Api can call another, otherwise it will cause function failure.



PO Function A – get battery


notice: Api calls must be one by one ,when the end of an Api can call another, otherwise it will cause function failure.



A-1: getBattery()

PO Function B – get offline data


notice: this function must call before function C.



B-1: getHistoryData()


PO FunctionC -measure online

notice: This function must call after function B.



C-1: startMeasure()

PO Function D - disconnect



D-1: disconnect()