

HS2 Overall Function

notice: Api calls must be one by one ,when the end of an Api can call another, otherwise it will cause function failure.



HS2 Function A – Get Battery


notice: Api calls must be one by one ,when the end of an Api can call another, otherwise it will cause function failure.



A-1: getBattery()

HS2 Function B - Get Offline Data


notice: Api calls must be one by one ,when the end of an Api can call another, otherwise it will cause function failure.



B-1: getOfflineData()


HS2 Function C - Measure Online

notice: Api calls must be one by one ,when the end of an Api can call another, otherwise it will cause function failure.



C-1: measureOnline(int unit, int userId)

HS2 Function D - Disconnect



D-1: disconnect()