
BP3I overall function

Note: Api calls one after another, that is, when the end of an Api, call the next, Otherwise it will appear the Api function failure.



A: getBattery ()

B1: startMeasure ()

B2: interruptMeasure ()

C: disconnect ()

Note: all methods are parallel ,no order. In measuring process, only racepte instruction B2.