

## BG5 overall function

Note: Api calls one after another, that is, when the end of an Api, call the next, Otherwise it will appear the Api function failure.



## BG5 FuncA – set parameters




A-1: public void getBattery()

A-2: public void setTime()

A-3: public void setUnit(int type)

## BG5 FuncB – getOfflineData


Note: before using BG5 offline measurement functions, you must call the Api (A–2), otherwise the offline data time may be wrong



B-1: public void getOfflineData()

B-2: public void deleteOfflineData()


## BG5 FuncC - sendCode



C-1: public void getBottleId()

C-2: public void getBottleMessage()

C-3: public void setBottleMessageWithInfo(int stripType, int measureType, String QRCode, byte stripNum, String overDate)



D-1: public void startMeasure(int type)

D-2: action\_measure\_strip\_in
D-3: action\_measure\_get\_blood

D-4: measure\_result

D-5: action\_measure\_strip\_out
D-6: action\_measure\_error