
BP5 overall function


Note: Api calls one after another, that is, when the end of an Api, call the next, Otherwise it will appear the Api function failure.



Note: all methods are parallel ,no order.

BP5 Function A - measure online

Note: Api calls one after another, that is, when the end of an Api, call the next, Otherwise it will appear the Api function failure. In measuring process, only racepte instruction A2




A1: startMeasure ()

A2: : interruptMeasure ()

BP5 Function B – upload offline data

Note: Calling api B1 first before measuring.




B1: isEnableOffine ()

B2: getOfflineNum ()

B3: getOfflineData()

BP5 Function C -offline setting




C1: isEnableOffine ()

C2: enableOffine ()


C3: disableOffine ()

BP5 Function D -get battery



D: isEnableOffine ()

BP5 Function E -disconnect



E: isEnableOffine ()