
#### BP7 overall function


Note: Api calls one after another, that is, when the end of an Api, call the next, Otherwise it will appear the Api function failure.



Note: all methods are parallel, no order.

### BP7 Function A - measure online

Note: Api calls one after another, that is, when the end of an Api, call the next, Otherwise it will appear the Api function failure. In measuring process, only racepte instruction A3




A1: getAngle ()

A2: startMeasure ()

A3: interruptMeasure ()

## BP7 Function B – upload offline data

Note: Calling api B1 first before measuring




B1: isEnableOffine ()

B2: getOfflineNum ()

B3: getOfflineData()

## BP7 Function C –offline setting




C1: isEnableOffine ()

C2: enableOffine ()


C3: disableOffine ()

# BP7 Function D –get battery



D: isEnableOffine ()

### BP7 Function E -disconnect



E: isEnableOffine ()