Process eggineering feem.

(admin) **Login** → Add New
~~Update~~ product
↓

New user
Forgot pass

P. Name	~~product~~ Equipart	Add
	Numb	A.S
		~~(Raf)~~
		(Any File)

↓

Click Home
↓

		Approve 9 of (Login)
Show all ↗ product	
Show pending ↓ ~~product~~	
	Approve	

1. Formet.

Product Name	Product part Num.	A.S (File)	DED AP. Status ↓ AP. by Dare.	Production. AP Statio. ↓ AP by Dare
Qlity A.P. Status (AP. by gate)	Hod Sfatus. (AP. Date)			

After HOD conform.

1. Formet

```
┌─────────────────────────────────────┐        ┌─────────┐
│                                      │        │ APprove │
│                                      │        │ sheet   │
│                                      │        └────┬────┘
└──────────────────────────────────────┘           ↓
```

~~PDF~~ Chick
↓

PDF File.
↓

```
┌──────────────────────────────┐   Dowton
│                              │
│  PED    Name    Date.        │
│  prouc  Name    Date.        │
│  Qtiy   Name    Date         │
│  Hod    Name    Date.        │
│                              │
└──────────────────────────────┘
```

Production

Login →

1.	P·Name	P·Num	big	AP.	(Pending)
2.	p·sion	P·Nu	ALS	A·P. (above)	
3.					
4.					

Name & Date.

Qlity

login
1.
2.

Produces
B[AP] (Pending
[AP] (above)

Red.

AP

[AP]

Dissable

view

Cicb
Name Date

HDD

(admin)

Login

links
→ product   qty .   HOD.
                        ↳
                      chick.
                        ↓
HOD PQ

prouct.   qlity   Hod.
Aprivd.   AP   AP.

                  completed.
                  ↳ Aploaded to
                operator   main pg.
                login.

Operator
Login → Part
Num.

Product   Part   Ais.
Name   Num